

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

WAB 1522442205 **6137** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Garry Michael
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-4895
Facility Name Cotton Draw Unit 89	Facility Type SWD

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-31381
------------------------------	------------------------------	-----------------------------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	31E	250'	FSL	1980'	FEL	Eddy

Latitude: 32.1528893

Longitude: -103.7636414

NATURE OF RELEASE

Type of Release Spill	Volume of Release 35bbl	Volume Recovered 25bbl
Source of Release 4" high pressure hose	Date and Hour of Occurrence August 6, 2015 5:04 PM	Date and Hour of Discovery August 6, 2015 5:04 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Mike Bratcher, OCD	
By Whom? Hubert Perry, Production Foreman	Date and Hour Jim Amos, August 6, 2015 7:35 PM Mike Bratcher, August 6, 2015 7:37 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* On August 6, 2015 5:04 at the Cotton Draw Unit 89 Truck Driver for Black River Trucking was loading produced water when the connecting high pressure 4" hose blew apart releasing 35bbls onto location. The well was immediately shut in and the next truck in line was Standard Trucking so they started recovering the released produced water immediately.		
Describe Area Affected and Cleanup Action Taken.* The affected area was approximately 80' x 120' x 50' all contained on location with 25bbls produced water recovered. The broken hose will be repaired. And environmental company will be contacted to determine the extent of clean up.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 8/11/15	Expiration Date: NA
E-mail Address: Sheila.Fisher@dyn.com	Conditions of Approval:	
Date: 8/11/15 Phone: 575.748.1829	Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 9/11/15	

* Attach Additional Sheets If Necessary

2RP-3198

Patterson, Heather, EMNRD

From: Fisher, Sheila <Sheila.Fisher@dvn.com>
Sent: Tuesday, August 11, 2015 4:11 PM
To: Jim Amos (jamos@blm.gov); Shelly Tucker (stucker@blm.gov); Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: Farley, Sandy; Nettles, Matt; Michael, Garry; Fulks, Brett
Subject: Cotton Draw Unit 89_35bbls produced water release_8.6.15
Attachments: Cotton Draw Unit 89_C-141_35bbl produced water release_8.6.15.doc; Cotton Draw Unit 89_GIS Image_35bbl produced water release_8.6.15.Word.docx; Cotton Draw Unit 89_35bbl produced water release_photo 1 of 5_8.6.15.jpg; Cotton Draw Unit 89_35bbl produced water release_photo 2 of 5_8.6.15.jpg; Cotton Draw Unit 89_35bbl produced water release_photo 3 of 5_8.6.15.jpg; Cotton Draw Unit 89_35bbl produced water release_photo 4 of 5_8.6.15.jpg

Good Afternoon,

Attached please find the Initial C-141, GIS Image and photos for the 35bbl produced water release at the Cotton Draw Unit 89.

If you have any questions please feel free to contact me.

Thank you,

Sheila Fisher
Field Admin Support
Production
A-Schedule

Devon Energy Corporation
PO Box 250
Artesia, NM 88211
575 748 1829 Direct



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.