Holly Energy Partners Navaho Apache DAD Lateral Closure Report

Section 30, T17S, R29E Eddy County, New Mexico

July 19, 2013



Prepared for:

Holly Energy Partners P.O. Box 1260 Artesia, New Mexico 88211

By:

Safety & Environmental Solutions, Inc. 703 East Clinton Hobbs, New Mexico 88240 (575) 397-0510

RECEIVED
AUG 0 1 2013
NMOCD ARTESIA

TABLE OF CONTENTS

l.	COMPANY CONTACTS	1
II.	BACKGROUND	1
III.	SURFACE AND GROUND WATER	1
IV.	CHARACTERIZATION	1
٧.	WORK PERFORMED	2
VI.	CONCLUSION	4
VII.	FIGURES & APPENDICES Figure 1 – Site Map Appendix A – Site Photographs Appendix B – C-141	4
F	igure 1 – Site Map	5
F	Appendix A – Site Photographs	8
F	Appendix B – C-141	18
P	Appendix C -RRAL Request Letter/ Approval E-Mail	20

I. Company Contacts

Representative	Company	Telephone	E-mail
Bill Green	Holly Energy Partners	575-748-8968	bill.green@hollyenergy.com
Bob Allen	SESI	575-397-0510	ballen@sesi-nm.com

II. Background

Safety and Environmental Solutions, Inc. (SESI) was contracted by Holly Energy Partners (HEP) to perform site assessment of a release area at the Navaho Apache DAD Lateral located in Section 30 of Township 17 South, Range 29 East, Eddy County, New Mexico.

According to the C-141, on October 22, 2011 a below ground release occurred due to internal corrosion of a 3" steel pipe tie-in from Concho Resources Navaho Federal #8. Clean-up crews were dispatched and free product was removed. Approximately 100 barrels of crude oil was released with an unknown amount recovered.

III. Surface and Ground Water

The nearest groundwater of record is approximately 2.9 miles northwest of the site in Section 22 Range 29 East and Township 17 South. The NM State Engineer Office reported depth in 2012 was 76 feet below ground surface (BGS). During a meeting with the local Oil Conservation Division (OCD) representative discussed personal knowledge of the last depth to water (DTW) measurement of an unmapped nearby well that was around 90' BGS. The surface relief of the site to the water well is in excess of 100'. This fact puts the likely DTW at the subject site to be well over the 100' BGS. (Appendix C)

IV. Characterization

The target cleanup levels are determined using the *Guidelines for Remediation of Leaks, Spills and Releases* published by the NMOCD (August 13, 1993). Based on the ranking criteria presented below, the applicable Recommended Remediation Action Levels (RRAL) are 10 parts per million (ppm) Benzene, 50 ppm combined benzene, toluene, ethylbenzene, and total xylenes (BTEX), and 5,000 ppm Total Petroleum Hydrocarbons (TPH).

Depth to Ground Water:							
(Vertical distance from contaminants to	Less than 50 feet	20 points					
seasonal high water elevation of	50 feet to 99 feet	10 points					
groundwater)	>100 feet	0 points	X				
Wellhead Protection Area:			-				
(Less than 200 feet from a private domestic	Yes	20 points					
water source; or less than 1000 feet from all	No	0 points	X				
other water sources)							
Distance to Surface Water:							
(Horizontal distance to perennial lakes,	Less than 200 feet	20 points					
ponds, rivers, streams, creeks, irrigation	200 feet to 1000 feet	10 points					
canals and ditches)	>1000 feet	0 points	X				
RANKING SCORE (TOTAL POINTS)							

V. Work Performed

On February 8, 2012, SESI installed four test trenches to determine the vertical extent of hydrocarbon impacts. Samples were retrieved, properly preserved, and transported under chain of custody to Cardinal Laboratories in Hobbs, New Mexico to be analyzed for TPH (EPA Method 418.1), and BTEX (EPA Method 8021B). The results are as follows:

Sample ID	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl - Benzene (mg/kg)	Total Xylenes (mg/kg)	TPH 418.1 (mg/kg)
Analysis Date:-	2/08/12	2/08/12	2/08/12	2/08/12	2/08/12
TT - 4 5' BGS	<0.050	<0.050	<0.050	<0.150	113
TT – 3 7' BGS	<0.050	<0.050	<0.050	<0.150	340
TT - 2 10' BGS	<1.00	19.9	23.7	41.7	5180
TT – 1 11' BGS	8.24	101	82.4	132	6790

On February 20, 2012, SESI installed two boreholes to a depth where the TPH concentrations were field tested to be below 1,000 ppm TPH. Samples were properly preserved and transported under chain of custody to Cardinal Laboratories in Hobbs, New Mexico for TPH (EPA Method 418.1), and BTEX (EPA Method 8021B) analyses. The results are as follows:

Sample ID	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl - Benzene (mg/kg)	Total Xylenes (mg/kg)	TPH 418.1 (mg/kg)
-Analysis Date:	2/20/12	2/20/12	2/20/12	2/20/12	2/20/12
BH - 1 19" TO 21" BGS	<0.050	<0.050	<0.050	<0.150	118
BH - 1 29" TO 31" BGS	<0.050	<0.050	<0.050	<0.150	<100
.BH - 2 19" TO 21" BGS	<0.050	<0.050	<0.050	<0.150	106
BH – 2 25" BGS	<0.050	<0.050	<0.050	<0.150	166

On November 05, 2012 SESI began excavating the southwest release area where the most pooling occurred. Field tested the soil and at the depths 8 ft., and 10 ft., 18 ft. and 20 ft. were performed during the excavation to determine the depth of contamination. A composite sample from the stockpile was retrieved, properly preserved and transported under chain of custody to Cardinal Laboratories. The results are as follows:

Sample ID	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl - Benzene (mg/kg)	Total Xylenes (mg/kg)	Total BTEX (mg/kg)
Analysis Date:	11/05/12	11/05/12	11/05/12	11/05/12	11/05/12
Stockpile C-1	8.15	68.0	56.9	103	236

Sample ID	GRO C6-C10 (mg/kg)	DRO >C10-C28 (mg/kg)	EXT DRO >C-28-C35 (mg/kg)
Analysis Date:-	11/05/12	11/05/12	11/05/12
Stockpile C-1	2010	5450	828

On April 26, 2013 SESI collected confirmation soil samples. Twenty-two samples were retrieved, properly preserved and transported under chain of custody to Hall Environmental Analysis Laboratory to be analyzed for DRO/GRO and BTEX. The results are as follows:

Sample ID.	DRO (mg/kg)	GRO (mg/kg)	Benzene (µg/L)	Toluene (µg/L)	Ethyl - Benzene(µg/L)	Total Xylenes(µg/L)
Analysis Date:-	5/6/13	5/6/13	5/6/13:22	5/6/13	5/6/13	5/6/13
AH-1 North Wall	41	ND	ND	ND	ND	ND
AH-2 North Wall	ND	ND	ND	ND	ND	ND
AH-3 North Wall	ND	ND	ND	ND	ND	ND
AH-1 South Wall	ND	ND	ND	ND	ND	ND
AH-2 South Wall	ND	ND	ND	ND	ND	ND ND
AH-3 South Wall	ND	ND	ND	ND	ND	ND
AH-1 Bottom 4' BGS	ND	ND	ND	ND	ND	ND
AH-2 Bottom 4' BGS	ND	ND	ND	ND	ND	ND
AH-3 Bottom 4' BGS	ND	ND	ND	ND	ND	ND
AH-4 Bottom 4' BGS	ND	ND	ND	ND	ND	ND
AH-5 West Wall	1100	12	ND	ND	0.22	0.052
AH-6 West Wall	ND	ND	ND	ND	ND	ND
AH-7 West Wall	ND	ND	ND	ND	ND	ND
AH-8 East Wall	460	11	ND	ND	0.12	0.37
AH-9 East Wall	900	10	ND	ND	0.086	0.29
AH-10 East Wall	ND	ND	ND	ND	ND	ND
AH-11 Bottom 6' BGS	870	42	ND	0.061	0.58	1.6
AH-12 Bottom 9' BGS	830	13	ND	ND	0.073	0.28
AH-13 Bottom 9' BGS	860	12	ND	ND	0.078	0.28
West Wall WP-10' BGS	11	ND	ND	ND	ND	ND
North Wall WP-8' BGS	85	ND	ND	0.065	0.11	0.24
Bottom WP-19' BGS	2000	130	ND	1.2	2.8	6.5

May 05, 2013 the bottom hole of excavation was cleaned out. The spoils from the excavation were hauled to R360 Environmental Solutions Land Waste Disposal. A total of 2,180 yards of contaminated soils was disposed. On May 21, 2013, SESI began backfilling the excavations.



VI. Conclusion

Remedial actions at this site have all been performed with the approval of, and in accordance with all New Mexico Oil Conservation Division (NMOCD) requirements


As a result, we respectfully submit this closure report for your consideration and approval.

VII. Figures & Appendices

Figure 1 – Site Plan Appendix A – Site Photographs Appendix B – C-141

Appendix C – RRAL Request Letter/Approval E-Mail

Figure 1 Site Map




Appendix A
Site Photographs




West Pit Excavation (Facing Southeast)




West Pit Excavation (Facing West)




West Pit Excavation (Facing West)



Excavation (Facing Northeast)



Excavation (Facing Northeast)




Excavation (Facing Northeast)



Excavation (Facing North)



Excavation (Facing Southwest)




Excavation (Facing South)



Excavation (Facing Southwest)




West Pit Excavation Back filled (Facing Southeast)



West Pit Excavation Back filled (Facing East)




West Pit Excavation Back filled (Facing East)



West Pit Excavation Back filled (Facing East)



Excavation Back filled (Facing South)




Excavation Back filled (Facing Southwest)



Excavation Back filled (Facing South)



Excavation Back filled (Facing Southwest)



West Pit Excavation Back filled (Facing Northeast)




West Pit Excavation Back filled (Facing East)



Excavation Back filled (Facing Northeast)



Excavation Back filled (Facing Northeast)



Excavation back filled (Facing South)



Excavation back filled (Facing South)

Appendix B C-141 District I
1625 N. Franch Dr., Hobbs, NM 88240
District II
1301 W. Gezed Avenno, Antonia, NM 88210
District III
1000 Rio Branco Road, Anton, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fo, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action												
			Keit	ase Norma								
		olly Energy		60310		Contact Jeff Stubblefield Telephone No. 972-322-5782						
		n Street Art		OAD Lateral			e Gathering Lin					
racinty Nat	TE MANA	IN LEGISIO /	whate r	AD LEIGH		racinty 1 yp	e comenting ran	1E				
Surface Ow	321	BLM		Mineral C	WDEI			Lease 1	ło.			
						N OF REI						
Unit Letter	Section.	Township	Range	Feet from the	North	/South Line		East/West Line		County		
	30	T17S	29E	1650°		FSL	2308	FEL		Eddy		
Latitude N 32' 48.167 Longitude W 104' 06.730 NATURE OF RELEASE												
Type of Rela		Crude Oi]				Release ~100 t		Recovered	bb 1		
Source of Re							our of Occurrence		Hour of Dis	covery		
3" steel pipel Was Immedia		irm?				10/22/2011 If YES, To	U/hom?	10:10 a	<u>ш</u>			
Was manage	es tantes c		Yes [No 🗌 Not Re	equired		wadus: le 575-626-1372					
By Whom?	Lori Comp	ज्यार्थ					omr 10/22/2011					
Was a Water	ourse Reac		Yes ⊠] No		H YES, Vo	dome Impacing t	he Waterrourse.				
If a Watercox	TES USIS TITI	nacted Descr	he Prily			<u>!</u>						
Describe Cause of Problem and Remedial Action Taken.* Possible internal or external corrosion on a 3" steel pipe tie-in from Conscho Resources Navacho Federal #8. The leak is located below ground at the tie-in of the Apache DAD lateral. Clean-up crews have been dispatched and free product will be removed. Contaminated soil will also be removed and placed on plastic near the site. Describe Area Affected and Cleanup Action Taken.* Lease road – nearest well: Concho Resources Navacho Federal #8. Lease road has been closed on both sides of release and earthen dikes built to prevent surface migration. The free product will be recovered and the contaminated soil will be excavated and placed on plastic to allow for restoral aeration. The soil will be handed to an approved land form conce analytical tests have been completed and the levels are at acceptable levels for disposal. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform connective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations bave failed to adequately investigate and remediate contamination that pass a threat to ground water, surface water, human health												
federal com	erleed in a	osmoo, russ es and/or res	XLD accep	Manute of a C-141	nebon (D65 D01 TEXAS	s ins obserna or)	esponsibility for c	oudinesce e	min any camer		
SCHOOL SHAPE	<u> بعدم</u>	week 1023			T		OIL CON	SERVATION	DIVISIO)N		
OIL CONSERVATION DIVISION												
Signature:						Approved by District Supervisor:						
Printed Name: Lori Compland												
Title:Mgr - I	Title:Mgr - Regulatory Compliance						Approval Date: Expiration I			Auto:		
E-mail Addr	E-mail Address: lori.com/hml/@hollyenergy.com						Conditions of Approval:					
Date:	10/22		ome: 575.	748.4076	i			_				
Attach Addi	iomai She	ets If Necess	arv									

Appendix C RRAL Request Letter/Approval E-Mail



P.O Box 1613 703 E. Clinton Hobbs, New Mexico 88240 575/397-0510 Fax 575/393-4388

Safety & Environmental Solutions, Inc.

May 15, 2013

Mr. Mike Bratcher New Mexico Oil Conservation Division 811 S. 1st Street Artesia, New Mexico 882110

Dear Mr. Bratcher:

The purpose of this letter is to request that Holly Energy Partners be allowed to revise the target cleanup level for the Navaho Apache DAD Lateral from 1000 ppm TPH as stated in the approved work plan dated August 20, 2012 to 5000 ppm TPH.

The reason for this request is the result of the discussion between you, Mr. Bill Green of Holly Energy Partners, and me on the day we met at the subject site regarding the depth to ground water is the area. The depth to water in the water well at the propane sales facility east of the subject site is reported by the New Mexico Office of the State Engineer on their website as 76' BGS. During our discussion, you mentioned that your personal knowledge of the last DTW measurement of that well was around 90' BGS. The surface relief of the subject site from the water well is in excess of 100'. This fact puts the tikely DTW at the subject site to be well over the 100'BGS required in the NMOCD Guidelines for the 5000 ppm target cleanup level.

Please approve this request and the site will be closed in the very near future as the samples of the sides and bottom of the current excavation are all below 5000 ppm TPH.

Thank you for your consideration in this matter.

Sincerely,

James R. Allen CSP, CHMM President

Osbelia Leyva

From:

Bratcher, Mike, EMNRD

Sent:

Friday, May 17, 2013 3:25 PM

To:

Bob Allen

Cc:

office2@sesi-nm.com; scontreras@sesi-nm.com; Green, Bill

Subject:

RE: Holly Energy Partners Navaho Apache DAD Lateral Target Cleanup Level Revision

Bob,

After reviewing OSE data for this Township/Range and OSE data for adjacent Township/Ranges, and in consideration of elevation differentials from the release site to the OSE documented well in S22-T17s-R29e, OCD agrees that while groundwater may exist beneath the release site, it would likely be encountered at a depth greater than 100' from surface. Your request for revision of the site ranking and clean up levels for this release site is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, please contact me.

Mike Bratcher NMOCD District 2 811 S. First Street Artesia, NM 88210 O: 575-748-1283 X108 C: 575-626-0857 F: 575-748-9720

From: Bob Allen [mailto:ballen@sesi-nm.com]

Sent: Friday, May 17, 2013 2:01 PM

To: Bratcher, Mike, EMNRD

Cc: office2@sesi-nm.com; scontreras@sesi-nm.com; Green, Bill

Subject: Holly Energy Partners Navaho Apache DAD Lateral Target Cleanup Level Revision

Mike.... Please review the attached letter and forward your approval for this revision ASAP. Thank you

Bob Allen CSP, CHMM Cell # 575.390.7063 Office # 575.397.0510 Fax # 575.393.4388

Isaiah 40:31

They that wait upon the Lord shall renew their strength; they shall mount up with wings as eagles; they shall run, and not be weary; and they shall walk, and not faint.

RECEIVED

OCT 0 9 2013

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1600 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources OCD ARTES:A

Submit I Copy to appropriate District Office in accordance with 19,15,29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr.

			-	<u> </u>	anta i	1e, NM 8/3	003					
			Rele	ease Notifi	catio	n and Co	orrective A	ction	,			
			OPERA'	Г	☐ Initial Report 🛛 Fi			Final Repo				
		olly Energy			Contact Jeff Stubbfield							
		n Street Arte		No. 972-322-57								
Facility Na	me <u>Navah</u>	o Federal/Ap	Facility Typ	e Gathering Li	ne							
Surface Ow	ner BLM			Mineral (Owner				API No).		
أكنده والمراجعين	हर किंदू गेड़ा स्टब्स्ट र	4		LOC	ATIC	N OF RE	FASE					
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	East/Wes	t Line		Cour	ıty
]	30	T17S	29E	1650'		FSL	2308'	FE.	L		EDD	Ϋ́
L	l	<u> </u>	 _	<u> </u>	<u> </u>		<u> </u>	J		<u>L</u>		
			L	atitude N 32' 4	8.167	Longiti	ude W 104' 06.	730				
				NA7	ruri	OF RELI	EASE					
Type of Rele	ase	Cr	ude Oil			Volume of	Release ~100	bbls V	olume f	Recovered		bbl
Source of Re							lour of Occurrence			Hour of Dis	covery	
3" steel pipel Was Immedi		Given?				10/22/2011 If YES, To			10:10 n.	m.		
Tras timicas	are storice.		Yes [No 🔲 Not R	equired		le 575-626-1372					
By Whom?	Lori Couple	and				Date and H	lour 10/22/2011	1:55 p.m.				
Was a Water	course Rea	ched?	N 157			If YES, Vo	lume Impacting t		ourse.			
			Yes 🛭			N/A						
If a Watercou	irse was Im	pacted, Descri	ibe Fully.	•								
N/A												
Describe Cou	se of Probl	em and Remed	dial Action	Taken *								
				el pipe tie-in from								
on plastic nea		. Clean-up cr	ews nave	been dispatched a	ina tree	product will b	e removed. Con	taminated s	on will	oc also be re	movec	and placed
												
Describe Area	Affected:	and Cleanup A	action Tak	en.*								
				aho Federal #8.								
				vered and the contest have been con								
mauteu to an a	pproved rai	id latin once a	matytical (est have been co	inpretec	and the levels	are acceptable a	evers for all	pusai.	see Attache	u C108	ute Report
I hereby certif	y that the i	nformation giv	ven above	is true and compl	cte to t	he best of my l	knowledge and u	nderstand tl	iat pursi	ant to NMC	CD n	iles and
regulations all	operators or the envir	are required to	report and	d/or file certain re e of a C-141 repo	ticase n	iotifications an c NMOCD ma	d perform correct	tive actions	for rele	ases which i	may en	idanger Tiability
should their o	perations h	ave failed to a	dequately	investigate and re	emediat	e contaminatio	on that pose a thre	at to groun	d water,	surface was	ter, hur	nan health
				ance of a C-141 i	report d	oes not relieve	the operator of r	esponsibili	ty for co	mpliance w	ith any	other
federal, state,	or local lav	s and/or regui	lations.				OIL CONS	EDVAT	TONI	OIVICIO	NI	
s /) . ^				1		OIL CONS	DERVAI	ION.	DIAIDIO	14	
Signature:	YOHL (ouplar	<u>rcl</u>				•					
Printed Name:	Lori Com	land	Approved by f	Environmental Sp	ecialist:							
11111001110110	2011 2011				_		··· ·					
Title: Mgr. Re	gulatory Co	ompliance ·				Approval Date	:	Expi	ration D	ate:		
E-mail Addres	s: lori.cour	oland@hoilver	ergy.com			Conditions of	Anproval:		Attached [
			one: 575,7				· · · · · · · · · · · · · · · · · · ·					
Date: 10/22												

^{*} Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

Osbelia Leyva <office2@sesi-nm.com> From: Sent:

Wednesday, October 09, 2013 1:54 PM

To: Bratcher, Mike, EMNRD

Subject: Final Report C-141 for Navaho Federal/Apache DAD Lateral

MX70403@hollycorp.com_20131009_111542.pdf **Attachments:**

Good Afternoon Young Man,

Attached please find the Final Report C-141 for Navaho Federal/Apache DAD Lateral for the closure report. If you have any questions, please feel free to give me a call at (575)397-0510.

Osbelia Leyva (Pepper)

Administrative Assistant Safety & Environmental Solutions, Inc.

Office: 575.397.0510 Fax: 575.393.4388

E-mail: office2@sesi-nm.com