



AE Order Number Banner

Report Description

This report shows an AE Order Number in Barcode format for purposes of scanning. The Barcode format is Code 39.



App Number: pSAD1327750394

1RP - 2966

OXY USA INC

HOBBS OCD

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

OCT 02 2013

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. USA INC. SRL 10/4/13	Contact	Austin Trammell
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8210
Facility Name	West Dollarhide Devonian Unit 101	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-12335

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	33	24S	38E	1980	North	779'	West	Lea

Latitude N 32.175350° Longitude W 103.0666°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	35 bbls	Volume Recovered	0 bbls oil
Source of Release	2" riser on well head broke off	Date and Hour of Occurrence	09/24/2012 9/24/13 WLP	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Austin Trammell	Date and Hour	09/24/2012 @ 2:31 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

DTW = 351' SRL
10/4/13



Describe Cause of Problem and Remedial Action Taken.*

A 2 inch riser on the well head broke off causing 35 bbls of produced water to leak onto the ground. No fluids were recovered and the riser was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 70'. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Austin Trammell	Approved by Environmental Specialist:  Environmental Specialist	
Title: HES Coordinator	Approval Date: 10/4/13	Expiration Date: 12/4/13
E-mail Address: Austin.Trammell@oxy.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 10/2/2013	Phone: (575) 397-8216	C-141 BY 12/4/13 IRP-10-13-2966

* Attach Additional Sheets If Necessary

h