

Kay C. Havenor

*Ph.D., Registered Geologist Arizona #30438
Certified Professional Geologist*

**Environmental - Hydrogeology
Remote Sensing - Resources**

Office: 505-624-4518

e-mail kay.havenor@gmail.com
904 Moore Avenue
Roswell, New Mexico 88201

June 1, 2017

Mr. Michael A. McMillan
Engineering Bureau NM OCD
1220 South St. Francis Drive
Santa Fe, NM 87505

Mr. McMillan,

The Mesquite SWD, Inc Paduca 6 SWD #1Y, SWD-1607, Lot 2, Sec. 6, T26S-R32E, Lea Co., API 30-025-43379 TD 18,881' (by Driller) penetrated 27' of upper-most Montoya. The mud-log sample descriptions, hydrocarbon detection, depth and drill-rate, in my opinion, indicate the Montoya is dense bedded dolomite with one thin layer of limestone that collectively will not accept nor yield fluid.

Respectfully submitted,

Kay Havenor