State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr.

Submit 2 Copies to appropriate District Office in accordance

Instrict IV 1220 South St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Side of fe						side of form						
			л. 							<u></u>		anne ann an ann an ann an an ann an an an an
			Kele	ase Notific				споп				
						OPERAT		⊠	Initia	Report		Final Report
Name of Co			Contact: Roy R. Rascon Telephone No.: 505-393-9174									
							e: Jct Box	[/4	·····			
Facility Nat	ne: Jusus	JCL 141-14			<u></u>	гасшиу тур	C. JCI DUA					
Surface Ow	ner: Beck	y Doom		Mineral O	wner:			I	lease N	0.:		
				LOCA	TIO	DN OF RELEASE						
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/Wes	West Line County			y
М	14	24	37								Lea	
		80	ι ,			<u>3 W</u> Longi OF REL	tude: <u>32*12.61</u> EASE	L	L	<u></u>		d
Type of Rele	ase: Produ	ced Water		11744	CIUS		Release: 20 bbls		olume Re	ecovered: () bbls	
			poly pipe	cracking 3"pvc		Date and Hour of Occurrence:			Date and Hour of Discovery:			
Was Immedia	ta Matian (liven?				N/A	Whom? N/A	4	6-05 17	25		
was minicula	ae nouce C		Yes 🔽	No 🖾 Not Re	couired	H 160, 10	WIDII: IWA					
By Whom?	N/A					Date and H	our: N/A					
Was a Water				······································		and the second s	lume Impacting t	he Waterco	ourse:	<u> </u>		
			Yes 🛛	No		N/A						
If a Watercou	urse was Im	pacted, Descr	ibe Fully.*	F			······································					
crack and ca Describe Are The leak affe	a Affected a ected a tota	elease. The 3 and Cleanup / l of 3816 sqft	" pvc spo Action Tak , of which	n Taken.* The 3" ol was replaced v zen. * 1 3432 sqft is pass diation work pla	with a 3	"poly spool.		-				
regulations al public health should their o	l operators a or the envir operations h oment. In a	are required to connent. The ave failed to a ddition, NMC	o report an acceptance idequately CD accept	is true and comp d/or file certain re- e of a C-141 repo investigate and re- tance of a C-141	elease no ort by the emediate	otifications ar NMOCD m contamination	d perform correct arked as "Final Roon that pose a three	tive actions eport" does eat to grour	o for relea not relie nd water,	ases which a we the oper surface was	may en ator of ter, hun	danger liability nan health
Ċ	.1 .	0:1	2				OIL CONS	SERVA	FION I	<u>DIVISIO</u>	¥ V	
Signature:	Riff	K. Kl.	Ð C	M					. [ŝ	Don. U		
Printed Name	Roy R	Rascon		(Approved by	District Supervise	or: 0.2.2.	مرجبه المرجرة	איזאיניג'יי	7	
		Project Lea	der			Approval Dat	e: 4-17-06		MEN Firation D		INEE	R
E-mail Addre	ss: rroyr	iceswd@lead	co.com			Conditions of	Approval:				-	
Date: 4.12.04	5		Dh	one: 505-393-91 '						Attached		
Attach Addin facil mai appl	tional Shee ty lent Water	ts If Necess FPAC OG - NPAC - NPAC	ary e1083 06108 20610	те: 505-393-91 2066 32273 832517	<u></u>					\bigcirc	\bigcirc	F. Y

Coperating Company

122 West Taylor • Hobbs, New Mexico 88240 Phone: (50) 393-9174 • Fax: (505) 397-1471

February 16, 2006

Paul Sheeley NMOCD Hobbs Office 1625 N. French Drive



RE: M-14 Leak Corrective Action Plan Justis Salt Water Disposal System UL/M SEC 14 T24S R37E

Dear Mr. Sheeley,

Rice Operating Company (ROC) discovered an accidental discharge at the above mentioned site on April 06, 2005. The release volume was approximately 20 barrels.

Characterization and delineation has been completed. Please find the attached Corrective Action Plan for this site. ROC is looking forward to hearing back from you on this submission and your approval is requested. If you have any questions please call me at (505) 631-2532.

Thank you,

Jennifer Johnson Environmental Technician Rice Operating Company

Enclosed: Lab results, driving directions, site map, Corrective Action Plan

JCOP

CORRECTIVE ACTION PLAN

SITE HISTORY

Rice Operating Company (ROC) discovered an accidental discharge at the above mentioned site which occurred on April 06, 2005. A 3-inch PVC line ruptured and was replaced with a 3-inch poly line. The volume of the release was 20 bbls. Groundwater depth is approximately 79 ft. A preliminary work plan submitted by ROC was approved by the District 1 office on June 28, 2005.

DELINEATION RESULTS

Delineation and characterization at this site was conducted according to the NMOCD approved work plan. On April 29, 2005 ROC conducted initial field analyses. On October 31, 2005 ROC used a backhoe to delineate the site further. Soil samples were collected and sent to the Environmental Lab of Texas for confirmation. After evaluating the test results from this site, ROC conducted a soil boring on sample point 'B' (see the enclosed site map) for additional characterization. Chloride concentrations show a conclusive decline with depth.

Upon completion of the site characterization and delineation this proposed remedy is protective of groundwater quality, human health, and the environment. The proposed remedy is the creation of an infiltration barrier through surface restoration and revegetation of the site.

PROPOSED CORRECTIVE ACTION

- 1. ROC will give driving directions to the contact company that will be performing the site restoration to submit a One-Call for pipeline location.
- 2. Areas highly impacted will be excavated to 3 ft, which is well below the root zone. These soils will be hauled to a NMOCD approved disposal facility.
- 3. Lower concentrations will be blended on site to concentrations that will support the growth of native vegetation.
- 4. ROC will haul in clean topsoil.
- 5. The topsoil will then be tilled and seeded with a blend of native vegetation. Fertilizer and water will be added as needed.
- 6. ROC will continue to monitor the site in the future for regrowth of vegetation.

ROC is the service provider (operator) for the Justis Salt Water Disposal System and has no ownership of any portion of the pipelines, wells, or facilities. The Justis Salt Water Disposal System is owned by a consortium of oil producers, System Partners, who provide all operating capitol on percentage ownership/usage basis. Environmental remediation projects of this magnitude may require System Partner AFE approval and work begins as funds are received.


Justis M-14 Release Unit 'M', Sec, 14, T17S, R35E

Soil Bore Delineation Field Tests


[CI] ppm	1994	1076	507	595	176	100
Depth bgs (ft)	15	20	25	30	35	40

Groundwater = 79 ft





Justis M-14 Leak Site



PLAN VIEW

*** not to scale ***

CHLORIDE FIELD TESTS

Backhoe Samples 10/31/05										
SP A		SF	°В	SP C		SF	D	SP E		
Depth	ppm	Depth	ppm	Depth	ppm	Depth	ppm	Depth	ppm	
1'	379	1'	856	1'	97	1'	730	1'	1046	
2'	835	2'	1568	2'	147	2'	609	2'	370	
3'	1040	3'	1181	3'	108	3'	1128	3'	754	
4'	1336	4'	1061	4'	177	4'	1559	4'	710	
5'	3080	5'	937	5'	116	5'	1844	5'	881	
6'	2795	6'	1131	6'	124	6'	1698	6'	763	
7'	3258	7'	1534	7'	142	7'	2321	7'	878	
8'	1815	8'	2464	8'	n/a	8'	2633	8'	373	
9'	1409	9'	2217	9'	n/a	9'	2077	9'	647	
10'	1623	10'	1718	10'	n/a	10'	1869	10'	402	
11'	1686	11'	2074	11'	n/a	11'	1734	11'	671	
11.5'	1458	12'	1560	12'	n/a	12'	1179	12'	547	

Soil B	ore 12/	12/05
Depth	ppm	Lab
10-15'	1994	
15-20'	1076	
20-25'	507	l
25-30'	595	
30-35'	176	92
35-40'	100	



DRIVING DIRECTIONS: Justis Jet M-14 UL/M Sec 14 – T24S – R37E

From the intersection HWY 18 and Cooper East Road north of Jal, turn east and go approx. 2.8 miles to double cattle guards, take south (right) cattle guard and go approx. 0.5th of a mile on lease road, at "Y" in the road just prior to caliche pit turn left. Jct box is located east of fence corner.

