

August 23, 2000

AUG 28

STATE OF NEW MEXICO  
Energy, Minerals and Natural Resources Dept.  
Oil Conservation Division  
Attention: Mr. David Catanach  
2040 S. Pacheco  
Santa Fe, NM 87505

RE: District II Pool Codes:  
Red Lake; Glorieta-Yeso (51120)  
Red Lake; Glorieta-Yeso, NE (96836)

Dear Mr. Catanach:

I received the pool maps that you sent regarding the above-referenced pools. As I suspected, in a couple of cases I have filed downhole commingling applications using the wrong pool codes. There is also an issue of some of our wells not being designated on any of the pool maps. The only wells that I know to be filed incorrectly are as follows:

**Eagle 34 J Federal #20 (API 30-015-29641)**

**Section 34-17S-27E, SE/4**

The well was deepened to the Yeso and downhole commingled with the existing San Andres. The downhole commingling application was incorrectly filed as Pool 51120, therefore the Administrative Order DHC-2685 was approved for Pool 51120. The well is actually in Pool 96836 and all of the subsequent recompletion reports, including the C-104, have been filed showing Pool 96836.

**Eagle 35 L Federal #1 (30-015-29090)**

**Section 35-17S-27E, SW/4**

The well was deepened to the Yeso and downhole commingled with the existing San Andres. The downhole commingling application was correctly filed as Pool 96836, however the Administrative Order DHC-2688 was approved for Pool 51120. The well is in Pool 96836.

**Logan 2 State #2 (API 30-015-30406)**

**Section 2-18S-27E, NW/4**

The well was originally drilled and completed in the Yeso. The C-104 was filed and approved in Pool 96836. The well was then recompleted in the San Andres and downhole commingled with the Yeso. The downhole commingling application was incorrectly filed as Pool 51120, therefore the Administrative Order DHC-2635 was approved for Pool 51120. The subsequent recompletion reports have been filed showing Pool 96836.

The following wells are not designated on any of the pool maps that you sent. Some have already been completed in the Yeso and others are approved to be deepened to the Yeso. Most of these wells have also had a downhole commingling application filed and approved. I will wait until I either hear from you or receive pool maps for these areas to determine if the downhole commingling orders reflect the correct Yeso pool and then I will notify you of any corrections that need to be made.

These wells have already been deepened or recompleted and downhole commingled.

Eagle 33 N Federal #9	Section 33-17S-27E, SW/4
Hawk 8 K Federal #3	Section 8-18S-27E, SW/4
Hawk 8 P Federal #11	Section 8-18S-27E, SE/4
Hawk 9 H Federal #11	Section 9-18S-27E, NE/4
Kaiser #1	Section 18-18S-27E, NE/4
Kaiser B #6	Section 18-18S-27E, NW/4

These wells have been approved to be deepened, but the work has not been done yet.

Hawk 17 C Federal #1	Section 17-18S-27E, NW/4
Hawk 8 K Federal #4	Section 8-18S-27E, SW/4
Hawk 8 L Federal #5	Section 8-18S-27E, SW/4
Hawk 8 O Federal #9	Section 8-18S-27E, SE/4
Hawk 9 O Federal #17	Section 9-18S-27E, SE/4
Hawk 9 P Federal #19	Section 9-18S-27E, SE/4
Falcon 3 B Federal #1	Section 3-18S-27E, NE/4
Falcon 3 G Federal #8	Section 3-18S-27E, NE/4
Falcon 3 J Federal #13	Section 3-18S-27E, SE/4
Kaiser #4	Section 18-18S-27E, NE/4
Kaiser B #3	Section 18-18S-27E, NE/4

Concerning the three wells that have incorrect pools listed on the Administrative Order, please let me know if I can simply make the correction on the order in my files. If you need any additional information, please call me (405) 552-4515.

Yours truly,

DEVON ENERGY PRODUCTION COMPANY, L.P.

Tonja Rutelonis  
Engineering Tech.

/trr

cc: E.L. Buttross, Jr.