District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003 ubmit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

					<u>O</u> I	PERATOR				al Report		Final Re	port	
Name of Co	mpany C	onocoPhilli	ps Comp	any		Contact Kenneth N. Andersen								
Address 40			62-5917	Telephone No. 505.391.3158										
Facility Nar	ne VGEU	West Batt		Facility Type Oil and Gas										
Surface Ow	ner State	of New Me	xico	Mineral ()wner	ner State of New Mexico Lease No B-2354-2						· · · · · · · · · · · · · · · · · · ·		
Surface OW	noi suite	01 11011 1110	······································											
				LOCA		N OF RE	LEASE							
Unit Letter	Section	Township	Range	Feet from the	Nort	h/South Line	Feet from the	East/W	st/West Line County					
A	31	17S	35E							Lea				
	<u></u>	<u> </u>	L		<u> </u>	·····		L		<u>L</u>				
	77'		Lat	titude 32.7972	282N	Longit	ide -103.4891	13W						
				NAT	TURI	E OF REL	EASE							
Type of Relea					olume of Release Volume Recovered									
		Water W/C	= Unknown						126 water)					
Source of Re					ı				Pate and Hour of Discovery 0/07/2006 0830hrs					
Was Immedia					10/07/2006 0730hrs 10/07/2 If YES, To Whom?				UO USJURIS					
was illineur		res No	Required		Patricia A. Caperton's voice mail									
						Pate and Hour 10/09/2006 0700hrs								
Was a Water		ched?			f YES, Volume Impacting the Watercourse.									
			Yes 🗵	No					;	β.,6+r.,				
If a Watercou	ırse was Im	pacted, Descr						•	Ç' :	ر ا				
										per les	14.			
Describe Cau	se of Probl	em and Reme	dial Action	1 Taken.*										
1					mp n	ot operating	causing the tan	ık to ov	er flow o	ut the thi e f	hatc	h. The		
The leak was caused by the produced water transfer pump not operating causing the tank to over flow out the thief hatch. The level control switches have been recalibrated. A vacuum truck was called and 130 bbls of fluid were recovered.														
Danadh a Ana	Describe Area Affected and Cleanup Action Taken.*													
					105" (of dry black o	oil/caliche rocl	k naetu	re with n	o cows nres	ent	The snill	1	
				accordance wi				k pastu	a C With h	o cows pres	cnt.	ine spin	•	
							knowledge and u							
							nd perform correct arked as "Final R							
							on that pose a thr						h	
							e the operator of							
federal, state,	or local la	ws and/or regi	ulations.	\sim		<u>, </u>			······································					
Ch in In						OIL CONSERVATION DIVISION								
Signature: Comet (Mersen														
23,		1		o par		Approved by	الدخا District S upervis	e Eug	P _ /	\cap				
Printed Name	: Kenneth	N. Andersei	1			Approved by	District Super vis	.or. C	30	<u> </u>				
Title: HSEF	PSM I AA	A				Approval Da	te: ((-70.0)	ر ا	\ Expiration	v Date: と・ る	ZD ~4	27		
Huc. HSEF	CI SIVI Lea	u				Appiovai Da	e. ((12010)		SAPIRATION	Date.				
E-mail Addre	ss: ken.n.a	ndersen@co	ps.com		Conditions of Approval:				Attached					
Date: 10/09	9/2006		505.391.3158		SuBMAFFORME C. 141				7 Hached					
	h Addition	nal Sheets If	Macaggar	u,			-, , , , , , , , , , , , , , , , , , ,		• • •		· ·	VII.	 ~	
, Don	· 0-4.	CPAI	1062	126196=	39						11	411	X	
gac	y	77/10		30/ HB>						11	' 10	U_		
facility -FPACO628649639 1 incident n PACO628649728 application - PPACO628649873										•	,			
	alica	tia -	o PAC	062864	48	13								
Cyf	gricu		[•										