

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form



Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Targa Midstream Services L P	Contact: James Lingnau 505.394.2534, Chula Tolama 505.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No. (505) 394-2534
Facility Name: Eunice Gathering System	Facility Type

Surface Owner: McCasland	Mineral Owner:	Lease No.
--------------------------	----------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
NE Corner	31	20S	39E					Lea

Latitude 32.33.806 N Longitude 103.05.492W

NATURE OF RELEASE

Type of Release: Gas and Produced Liquids	Volume of Release: Gas and estimated less than 5 barrels of liquid.	Volume Recovered: None
Source of Release: 4" Gas Gathering Pipeline Failure, Line pressure 12#, Volume of throughput 30mc/d, Line depth 4 feet, Less than 50 ppm H2S,	Date and Hour of Occurrence:	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken. *

A Four inch gathering line had a leak and released gas and any produced liquids that were lying in the line. Field operators immediately blocked in line. Repairs were made to the line and area was treated by bio-remediation. Line started to leak again and reported to TARGA..

Describe Area Affected and Cleanup Action Taken.*

Targa has replaced two sections of steel line with poly line. Targa is in the process of removing contaminated soil. The area will be cleaned and tested per OCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Embrey</i>	OIL CONSERVATION DIVISION	
Printed Name: Don Embrey	Approved by District Supervisor: <i>ENV 122 ENGE</i>	
Title: Advisor	Approval Date: <i>4-25-07</i>	Expiration Date:
E-mail Address: dembrey@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/15/07	Phone: (432) 688-0546	

* Attach Additional Sheets If Necessary

incident - NPAC 0711549674
application - PPAC 0711549803

RP# 1290