

1RP#1301 Approved 10-3-07 LJ

From: Jerri Lee [mailto:office@sesi-nm.com]
Sent: Tuesday, October 02, 2007 8:12 AM
To: Johnson, Larry, EMNRD
Cc: jimmyc@forl.com
Subject: Fasken Denton SWD #5 Delineation Report/workplan

Larry have you had a chance to look over this?

Larry attached please find the workplan for the Fasken Oil Denton SWD #5 cleanup. Please review and forward your approval or any stipulations. A hard copy will follow by mail.

Thank you,

Jerri Lee
Administrative Assistant

This inbound email has been scanned by the MessageLabs Email Security System.

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

*"CORRECTED
VOLUMES"*
RP# 301

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Fasken Oil and Ranch, Ltd.	Contact Jimmy D. Carlile
Address 303 W. Wall, Ste 1800 Midland, TX	Telephone No. 432 687-1777
Facility Name Denton SWD No. 5	Facility Type Salt Water Disposal

Surface Owner Darr Angell	Mineral Owner Fee	Lease No.
----------------------------------	--------------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	15S	37E	660	south	1980	west	Lea

Latitude _____ Longitude _____ *WATER 45'*

NATURE OF RELEASE *20 BW*

Type of Release salt water/oil	Volume of Release 185 BO	Volume Recovered 180 BO
Source of Release stock tank	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? 4/26/07 1 am 4/26/07 1 am	
By Whom? Jimmy D. Carlile	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*


Injection pump failed. Pump to be repaired.

Describe Area Affected and Cleanup Action Taken.*

Area affected inside of bermed facility. Fluids picked up by vacuum trucks.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jimmy D. Carlile</i>	OIL CONSERVATION DIVISION	
Printed Name: Jimmy D. Carlile	Approved by District Supervisor: <i>[Signature]</i>	
Title: Regulatory Affairs Coord.	Approval Date: 5.18.07	Expiration Date: 7.18.07
E-mail Address: jimmyc@for1.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4/26/07 Phone: 432 687-1777		




* Attach Additional Sheets If Necessary

Incident - n PAC0714248443
applicat - p PAC0714248548

RP# 301

**Fasken Oil and Ranch, LTD.
Denton SWD #5
Delineation Report/Work Plan
Unit N, Section 2, Township 15S, Range 37E
Lea County, New Mexico**

September 12, 2007



IRP 1301

Prepared for:

**Fasken Oil and Ranch, LTD.
303 W. Wall Suite 1800
Midland, Texas 79701-5116**

By:

***Safety & Environmental Solutions, Inc.
703 E. Clinton Suite 102
Hobbs, New Mexico 88240
(505) 397-0510***

TABLE OF CONTENTS

I. COMPANY CONTACTS	1
II. BACKGROUND	1
III. SURFACE AND GROUND WATER	1
IV. SOILS	1
V. WORK PERFORMED	1
VI. ACTION PLAN	2
VII. FIGURES & APPENDICES	2
Figure 1 – Vicinity Map	3
Figure 2 – Site Plan	4
Figure 3 – Logs of Boring.....	5
Appendix A – C-141.....	6
Appendix B – Analytical Results	7
Appendix C – Site Photos	8

I. Company Contacts

NAME	Company	Telephone	E-mail
Jimmy Davis	Fasken	432-818-0267	jimmyd@forl.com
Jimmy Carlile	Fasken	432-818-0210	jimmyc@forl.com
Bob Allen	SESI	505-397-0510	ballen@sesi-nm.com

II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by Fasken Oil and Ranch, LTD. to perform cleanup services at the Denton SWD #5 Tank Battery. The facility was affected by an overflow in the tanks caused by an injection pump failure. Approximately 205 barrels of produced fluid were released, 195 barrels were recovered. The spill was contained inside the bermed area.

III. Surface and Ground Water

The closest groundwater of record listed with the New Mexico office of the state engineer is located in the same section, range and township. The depth of water in this well was 47' in 1974. SESI has a monitor well installed approximately 3,634 northeast of this site. The depth of water in this well was 69.41' in March of this year.

IV. Soils

The surface soils in the area are predominantly sand and sandy loam.

V. Work Performed

On August 29, 2007 SESI installed four (4) soil borings inside the spill area to determine the vertical extent of contamination. Borehole #1 was drilled to a depth of 20', Borehole #2 was drilled to a depth of 15' and Boreholes #3 and #4 were drilled to a depth of 10'. Samples were retrieved in 5' intervals from all boreholes. All samples were properly preserved and transported under Chain of Custody to Argon Laboratories of Hobbs, New Mexico for analysis. The samples were analyzed for Total Petroleum Hydrocarbons (EPA Method 418.1), BTEX (EPA Method SW-846-8260), and Chlorides (EPA Method 4500-Cl⁻B).

The results of the analysis are as follows:

Date	Sample ID	Cl ⁻ (mg/kg)	TPH (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl Benzene (mg/kg)	Total Xylenes (mg/kg)
8/29/07	BH #1-5'	800	180	ND	ND	ND	ND
8/29/07	BH #1-10'	720	55	ND	ND	ND	ND
8/29/07	BH #1-15'	180	ND	ND	ND	ND	ND
8/29/07	BH #1-20'	140	ND	ND	ND	ND	ND
8/29/07	BH #2-5'	190	4500	ND	ND	0.23	1.9
8/29/07	BH #2-10'	180	3400	ND	ND	0.19	1.4
8/29/07	BH #2-15'	53	ND	ND	ND	ND	ND
8/29/07	BH #3-5'	120	3000	ND	ND	0.33	4.1

Date	Sample ID	Cl ⁻ (mg/kg)	TPH (mg/kg)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl Benzene (mg/kg)	Total Xylenes (mg/kg)
8/29/07	BH #3-10'	90	870	ND	ND	0.017	0.19
8/29/07	BH #4-5'	320	1200	ND	ND	ND	0.040
8/29/07	BH #4-10'	150	140	ND	ND	ND	ND

All borings were backfilled from total depth to surface with bentonite.

VI. Action Plan

It is proposed that a cosmetic cleanup, consisting of the removal of the top 12"-15" inches of soil, be performed around the tank battery. The remaining spill area will be excavated for the removal of the most highly contaminated and/or saturated material. The excavated soils will be transported to an NMOCD approved facility for disposal. The excavations will then be backfilled with clean soils.


This is an active tank battery and the operator is fully aware that at such time the battery and lease is abandoned, additional cleanup may be required.

Upon completion a closure report will be submitted to the NMOCD.

VII. Figures & Appendices

- Figure 1 – Vicinity Map
- Figure 2 – Site Plan
- Figure 3 – Logs of Boring
- Appendix A – C-141
- Appendix B – Site Photos

Figure 1
Vicinity Map



3807

3804

3796

6941

Refinery

47'

Denton SWD #5

3804

3795

Dickinson Ranch

Gravel Pit

32

3813

10

11

OIL

DENTON

Copyright © 2000 by [illegible]

**Figure 2
Site Plan**




Figure 3
Logs of Boring

Appendix A

C-141

