

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (505) 397-8251
Facility Name South Hobbs Unit Injection System	Facility Type Production

Surface Owner State of New Mexico	Mineral Owner Occidental Permian Limited Partnership	Lease No.
--------------------------------------	---	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line
'K'	4	19-S	38-E				

Latitude North 32°41'12.40" Longitude West 103°09'17.90"

NATURE OF RELEASE


Type of Release Produced and Injection Water	Volume of Release 2 BO X 250 BW	Volume Recovered 0 Bbls
Source of Release 8" cement lined steel injection trunk line	Date and Hour of Occurrence 10/03/2007 02:30 PM	Date and Hour of Discovery 10/03/2007 02:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink	
By Whom? Steven M. Bishop	Date and Hour 10/03/2007 05:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A


Describe Cause of Problem and Remedial Action Taken.* An 8" cement lined steel injection trunk line from South Hobbs Unit Central T/B to South Hobbs Unit Injection Building #1 split causing spill. Isolated the trunk line by shutting valves at both ends.

Describe Area Affected and Cleanup Action Taken.* Area affected is approximately 75' X 150' of pasture to the northwest of leak site and an area to the southeast of the leak site approximately 100' X 300' where water ran. No fluid was recovered. Piping will be repaired, and samples will be taken in affected area to insure area is in compliance with NMOCD guidelines for spills. Vegetation will be monitored for impact where water ran from leak site, minimal impact is expected. Occidental Permian LTD. leases this site from the State of New Mexico.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop	 Approved by District Environmental Engineer	
Title: HES Technician	Approval Date: 10.9.07	Expiration Date: 12.10.07
E-mail Address: Steven_Bishop@oxy.com	Conditions of Approval:  Attached <input type="checkbox"/>	
Date: 10/04/2007 Phone: (505) 397-8251	SUBMIT DELINEATION BY	

* Attach Additional Sheets If Necessary



RP# 1611

SPILL MAP


PLEASE DRAW SKETCH OF SPILL AND INDICATE WHERE SPILL ORIGINATED.

ULK Sec. 4, T-19-S, R-38-E
N 32° 41', 12.40" W 103° 09' 17.90"
OCD PAGER 5:15 PM
ARY WINK 5:20 PM

SOUTH HOBBS UNIT INJECTION TRUNKLINE
8" Cement lined pipe
10/03/2007 2:30 PM
estimate 2 BOX 250 BW
Ø Recovered
150yds NW OF SHU # 141



SHU
SATELLITE
#5





Occidental Permian Limited Partnership

October 4, 2007

New Mexico Oil Conservation Division
District I
1625 N. French Drive
Hobbs, New Mexico 88240



Attn: Environmental Engineering

RE: Remediation Plan
South Hobbs Unit 8" Injection Trunk line
from Central T/B to Injection Building #1
UL 'K', Sec. 4, T-19-S, R-38-E


Leak occurred on 10/03/2007, at approximately 02:30 PM. An 8" cement lined steel trunk line used to transfer injection water from South Hobbs Unit Central T/B to South Hobbs Unit Injection Building #1 split causing spill. Valves on both ends of the trunk line were shut to isolate leak. The line operates at approximately 1100 pounds and has a rate of approximately 16,000 barrels per day. The exact throughput of the line is unknown since there are two trunk lines that transfer injection water to this injection building. The injection line also damaged a fiberglass production line serving South Hobbs Unit Satellite #5. The area affected by this spill is an area measuring approximately 75' X 150', in the pasture north and west of the spill site, and an area approximately 100' X 300' in the pasture to the south and east of the leak site where water ran. An estimated 250 barrels of injection water and 2 barrels oil was spilled. All fluid was lost, none was recovered. The State of New Mexico is the surface owner. Oxy Permian leases the area from the State of New Mexico and utilizes the surface for oil and gas production only. Depth to ground water according to State Engineers Office is an average of 48', for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site will be as follows:

1. Piping will be repaired.
2. Soil samples will be gathered from affected area.
3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.
4. Soils removed will be replaced with clean fresh soils, where needed.
5. Soil analysis data will be submitted with final closure letter.
6. Affected area will be monitored for vegetation impact, expect minimal impact due to water.

October 4, 2007

Page 2

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

A handwritten signature in black ink that reads "Steven M. Bishop". The signature is written in a cursive style with a large, looping initial 'S'.

Steven M. Bishop
HES Technician/WSAH RMT
Steven_Bishop@oxy.com
(505) 397-8251

Attachments: Initial C-141
Hand drawn map of spill site
Analytical data of South Hobbs Unit Injection Water dated 8/15/2007