

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUL 03 2008

HOBBS OCD

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☐ Final Report

Name of Company	COG OPERATING LLC	Contact	Kanicia Carrillo
Address	550 W. Texas, Suite 1300 Midland, TX 79701	Telephone No.	432-685-4332
Facility Name	Pronghorn SWD #1	Facility Type	SWD
Surface Owner	STATE	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

API 30-025-32735

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	13	19S	32E	330	North	1650	East	Lea

Latitude 32.66708 Longitude 103.72023

WTR 200't

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	9,950 bbls	Volume Recovered	1745 bbls
Source of Release	Buried PVC pipe	Date and Hour of Occurrence	Aprox 06/24/08 8:00 am	Date and Hour of Discovery	06/25/08 6:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Larry Johnson (OCD)		
By Whom?	Kent Greenway	Date and Hour	06/25/08 5:00pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



8" PVC injection line had a crack in the PVC pipe. Dug out the line and fixed line, cut out bad pipe and replaced, vacuum truck picked up fluid. We thought leak was fixed but when the SWD was turned back on the same part in the PVC pipe was still leaking. We cut out the bad PVC pipe and replaced it, called vacuum truck to pick up fluid.

Describe Area Affected and Cleanup Action Taken.*

The PVC pipe leaked out over a 200' x 400' area.
The PVC pipe was contained within the pipe trench about 8' x 100' trench area was affected.

Removed soil and hauled to land fill. Highland Environmental will send a remediation report and Ark survey.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kanicia Carrillo	Approved by District Supervisor: 	
Title: Regulatory Analyst	Approval Date: 7.9.08	Expiration Date: 9.9.08
E-mail Address: kcarrillo@conchoresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/30/08 Phone: 432-685-4332	Submit Final C-141 w/	IRP# 1901

* Attach Additional Sheets If Necessary

FGRL0822435121

Closure Report 34 9.9.08



JOB NO. 3551

40


१०

Prologues

NAME:

700

OK Hand 200
bought 10-12



1910 N. Big Spring • Midland, Texas 79705 • (432) 682-4559 • Fax (432) 682-3946

Fax (432) 682-3946