

District I
1625 N French Dr., Hobbs, NM 88240

District II
1301 W. Grand Avenue, Artesia, NM 88210

District III
1000 Rio Brazos Road, Aztec, NM 87410

District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Holly Energy Partners	Contact	Dickie Townley
Address	P.O. Box 1260	Telephone No.	575-748-8949
Facility Name	Monument Station	Facility Type	Crude Storage

Surface Owner	Holly Energy Partners	Mineral Owner	??	Lease No.	N/A
---------------	-----------------------	---------------	----	-----------	-----

LOCATION OF RELEASE API# 30.025.20299.00-00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	10	20S	37E					Lea

Latitude 32.58403 N Longitude 103.24777 W 10-29-08 10-29-08

NATURE OF RELEASE

Type of Release	Liquid / Crude Oil	Volume of Release	25	Volume Recovered	
Source of Release		Date and Hour of Occurrence	Midnight to 8:00 AM	Date and Hour of Discovery	8:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Buddy Hill (District I)		
By Whom?	Dickie Townley	Date and Hour	10-29-08 @ 3:05 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.* Tank overfill & high level alarm failure. Storage tank is bypassed while operations group investigates cause of alarm failure. Tank will be put back in service once problem is identified & fixed.

Describe Area Affected and Cleanup Action Taken.* The area inside the tank dike & north of tank.

The area north of the tank had a light oil cover due to wind blowing oil from top of tank. Free product was vacuumed. Contaminated soil was excavated & placed on plastic. Samples were taken. Soil will be removed depending on lab analysis.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Richard L. Townley	OIL CONSERVATION DIVISION		
Printed Name: Richard L. Townley	Approved by District Supervisor ENVIRONMENTAL ENGINEER.		
Title: Manager of Environmental Health & Safety	Approval Date: 12.12.08	Expiration Date: 2.12.09	
E-mail Address: dickie.townley@hollyenergy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10-29-2008 Phone: 575-748-8949	SUBMIT FINAL C-141 w/ DOCUMENTATION		IRP# 2027

* Attach Additional Sheets If Necessary

↑
INCLUDE # ON ALL
SUBMITTALS PERTAINING
TO THIS INCIDENT

FILED 0835150285