

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87501

RECEIVED

APR 13 2009

HOBBSSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (575) 397-8251
Facility Name South Hobbs Unit #162	Facility Type Production

Surface Owner State of NM and Oxy Permian	Mineral Owner	Lease No. API 30-025-28365
---	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
'H'	5	19-S	38-E					LEA

Latitude N32.67502° Longitude W103.14615°

NATURE OF RELEASE



Type of Release Report of Fire	Volume of Release 0 BBLS	Volume Recovered 0 BBLS
Source of Release Fuse blew on electrical pole	Date and Hour of Occurrence 04/09/2009 02:45 PM	Date and Hour of Discovery 04/09/2009 02:45 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left Message for Mr. Buddy Hill	
By Whom? Steven M. Bishop	Date and Hour 04/09/2009 3:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully. * N/A

Describe Cause of Problem and Remedial Action Taken. * ☐ A contract employee was troubleshooting the 2500V/300A electric panel at the South Hobbs Unit Well #162 location. He went to turn off the disconnect on the panel and a malfunction caused the panel not to disconnect. The panel started arcing and blew a fuse on the electrical pole. A spark from the fuse reached the ground causing a small grass fire. The contractor called 911 and the Hobbs Fire Department did respond to extinguish the grass fire. No injuries due to this event. Damage only to Oxy electrical panel.

Describe Area Affected and Cleanup Action Taken. * ☐ Approximately 3 to 5 acres of grassy pasture burned before fire could be extinguished. Electrical panel will be repaired or replaced. No injuries occurred due to this event.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop	Approved by ENV ENGR District Supervisor: 	
Title: HES Specialist	Approval Date: 04/13/09	Expiration Date: —
E-mail Address: Steven_Bishop@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 04/10/2009 Phone: (575) 397-8251		IRP-09-4-2154

* Attach Additional Sheets If Necessary

FGRL0910358118