

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
JUL 29 2009
HOBBSOCD

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report XX Final Report

Name of Company	Oxy USA WTP	Contact	Dusty Wilson
Address	1017 W. Stanolind Rd	Telephone No.	(575) 397-8247
Facility Name	Lee Stebbins A & B Battery	Facility Type	Storage Facility

Surface Owner	Bull Henson	Mineral Owner		Lease No.	
---------------	-------------	---------------	--	-----------	--

LOCATION OF RELEASE

LEE STEBBINS NCTA 005
API # 30.025.36397.00.00

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	5	22s	37e					Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produce Water	Volume of Release	140 bbls	Volume Recovered	130 bbls
Source of Release	Internal corrosion, flow line	Date and Hour of Occurrence	06/21/2009	Date and Hour of Discovery	06/21/2009 @ 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jeff LeKing		
By Whom?	Dusty Wilson	Date and Hour	06/22/09 @ 8:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	n/a		

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*


Flow line at transfer pump separated causing produce water to spill into battery area. Spill stayed within battery secondary containment walls. Secondary containment is lined with plastic bladder, showing to be intact and in good working condition. Majority of produce water was recovered via vac truck at the time of discovery. Remediation efforts listed below. Remediation is complete.


Describe Area Affected and Cleanup Action Taken.*

Remediate to NMOCD Requirements. Remediation efforts consisted of removing 2" soil that covered the bladder of the batteries secondary containment and disposing of it at Sundance Services< Eunice NM. Re-covering the bladder with clean like material. Remediation efforts are complete

Approved By Jeff LeKing (Via Telephone) 6/23/09 @ 3:00 pm

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 
Printed Name: Dusty L. Wilson
Title: HES Specialist
E-mail Address: dusty_wilson@oxy.com
Date: 06/30/2009 Phone: (575) 397-8210

OIL CONSERVATION DIVISION
ENV. ENGINEER
Approved by District Supervisor: 
Approval Date: 08/17/09 Expiration Date: _____
Conditions of Approval: _____ Attached
IRP-09-8-2262

- Attach Additional Sheets If Necessary

FGRL0922928346