

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-23721
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Patsy
8. Well No.	001
9. Pool name or Wildcat	Langlie Mattix Seven Rivers Q
	Grayburg
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3375 GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BANNER DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Bettis, Boyle & Stovall	
3. Address of Operator P.O. Box 1240, Graham, TX 76450	
4. Well Location Unit Letter B : 990 Feet From The North Line and 1980 Feet From The East Line Section 20 Township 22S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3375 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work) SEE RULE 1103.
- 1) MIRU Pulling Unit
 - 2) POOH with rods & pump & 2-3/8" tbg.
 - 3) RIH with 2-3/8" tbg. open ended & pump 25 sxs. cement from 3400 to 3250' - TAG
 - 4) Cut 5-1/2" csg. @ 2000', POOH with 5-1/2" csg.
 - 5) RIH with 2-3/8" tbg. & pump 25 sxs. cement from 2050 to 1950' - TAG
 - 6) POOH with 2-3/8" tbg. & pump 30 sxs. plug from 348 - 248' - TAG
 - 7) Place 5 sxs. plug @ surface. - 105K OR 60'
 - 8) Cut csg. off 4' below ground level & weld on plate.
 - 9) Clean up location.

Estimated date to plug and abandon is June to July 2002.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Derrick Salter TITLE District Engineer DATE 10/29/01
TYPE OR PRINT NAME DERICK SALTER TELEPHONE NO. _____

(This

APR
CON

Post subsequent to RBDMS
Compliance Screen

ORIGINAL SIGNED BY
GARY W. WINK
TITLE NATURAL SCIENCE MANAGER - 2

DATE NOV 14 2001

BETTS, BOYLE - STOWALL
 PATSY A #1
 LEA CO. N.MEXICO

22-141 50 SHEETS
 22-142 100 SHEETS
 22-144 200 SHEETS



12 1/4" hole →

298' - 8 5/8" - 24#/FT
 CMT'D W/ 265 SXS TO SUR

7 7/8" hole →

TOC @ 2200'

3469
 3587
 QUARTZ FORMATION

OLD Puffs

3822
 3899

008

CIBP @ 3780' W/ 20' CMT ON TOP
 PBT @ 3760'

5 1/2" - 14 Lsg @ 9000'
 CMT'D W/ 450 SXS

OCT 1967
 RECEIVED
 Hobbs
 OCD