
Submit 3 Copica To Appropriate District	State of New Mexico	Form C-1
District 1	Energy, Minerals and Natural Resources	May 27, 20
1625.N French Dr , Hobbs, NM 88240		WELL API NO.
District II 1301 W Grand Ave , Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-01838
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM 87505		VO 6256
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH	STATE X
	Gas Well 🛛 Other	8. Well Number 1
2. Name of Operator		9. OGRID Number
PRIDE ENERGY COMPANY		151323
3. Address of Operator PO BOX 701950, TULSA, OK 741	70	10. Pool name or Wildcat RANGER LAKE MORROW, NORTH
4. Well Location		
Unit Letter E :	1980 feet from the NORTH line and	660 feet from theWESTli
Section 12	Township 12S Range 34E	NMPM LEA County
Part of the second s	11. Elevation (Show whether DR, RKB, RT, GR,	
The second s	4151' RKB	α.) Α. 16.1516./
Pit or Below-grade Tank Application . o		
		Distance from nearcst surface water
Pit Liner Thickness: mil		Construction Material
12. Check A	appropriate Box to Indicate Nature of Notic	ce, Report or Other Data Hobbs
		JBSEQUENT REPORT OF
NOTICE OF IN		JBSEQUENT RERORI OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛 🛛 REMEDIAL W	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE I	DRILLING OPNS. PANDAE0867
PULL OR ALTER CASING	MULTIPLE COMPL	ENT JOB
OTHER:		
<ol> <li>Describe proposed or comp of starting any proposed wo</li> </ol>	OTHER:           leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated Attach wellbore diagram of proposed comple
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> </ol>	leted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated Attach wellbore diagram of proposed comple
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:	Attach wellbore diagram of proposed comple
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>RUPU. Calculate freepoint of 2-"</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen	Attach wellbore diagram of proposed complete the sent plug w/ dump bailer. WOC.
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>RUPU. Calculate freepoint of 2-'</li> <li>2) Set CIBP @ 11,880' and cap w/ 3</li> </ol>	<ul> <li>leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:</li> <li>7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen</li> <li>5' cement plug. Cut off 2-7/8" tubing above free</li> </ul>	Attach wellbore diagram of proposed complete the sent plug w/ dump bailer. WOC.
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>RUPU. Calculate freepoint of 2-'</li> <li>2) Set CIBP @ 11,880' and cap w/ 2</li> <li>cement plug at tubing stub WOC, t</li> </ol>	<ul> <li>leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:</li> <li>7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cents' cent plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing.</li> </ul>	Attach wellbore diagram of proposed complete nent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>1) RUPU. Calculate freepoint of 2-2</li> <li>2) Set CIBP @ 11,880' and cap w/22</li> <li>cement plug at tubing stub WOC, to 3) Weld lift sub on 5-1/2" casing</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre	Attach wellbore diagram of proposed complete ment plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>1) RUPU. Calculate freepoint of 2-2</li> <li>2) Set CIBP @ 11,880' and cap w/2</li> <li>cement plug at tubing stub WOC, t</li> <li>3) Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk pluge-ir</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre pepen-hole) at top of Wolfcamp (9225'), Drinkard (	Attach wellbore diagram of proposed complete nent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164').
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>1) RUPU. Calculate freepoint of 2-2</li> <li>2) Set CIBP @ 11,880' and cap w/22</li> <li>cement plug at tubing stub WOC, t</li> <li>3) Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk pluge-ir</li> <li>4) Shoot off 5-1/2" casing and jack of</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre <del>spen hole</del> ) at top of Wolfcamp (9225'), Drinkard four bout of hole until rig can pull remaining pipe. Finisl	Attach wellbore diagram of proposed complete nent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing.
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>1) RUPU. Calculate freepoint of 2-2</li> <li>2) Set CIBP @ 11,880' and cap w/2</li> <li>cement plug at tubing stub WOC, t</li> <li>3) Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk plugo-ir</li> <li>4) Shoot off 5-1/2" casing and jack of</li> <li>5) TIH w/ 2-7/8" tubing. Spot and</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard to but of hole until rig can pull remaining pipe. Finisl tag plug 50' in and 50'out of stub. Spot remaining	Attach wellbore diagram of proposed complete nent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p
<ol> <li>13. Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2</li> <li>Set CIBP @ 11,880' and cap w/ 3</li> <li>cement plug at tubing stub<b>X</b> WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk pluga ir 4) Shoot off 5-1/2" casing and jack of 5) T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed</li> </ol> </li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre <del>pepen hole</del> ) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finisl tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface.
<ol> <li>13. Describe proposed or comp of starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure:</li> <li>1) RUPU. Calculate freepoint of 2-2</li> <li>2) Set CIBP @ 11,880' and cap w/2</li> <li>cement plug at tubing stub WOC, t</li> <li>3) Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk plugo-ir</li> <li>4) Shoot off 5-1/2" casing and jack of 5) T1H w/ 2-7/8" tubing. Spot and</li> <li>25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7) Restore location.</li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard to but of hole until rig can pull remaining pipe. Finisl tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface.
<ol> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2-2</li> <li>Set CIBP @ 11,880' and cap w/2</li> <li>Set CIBP @ 12,880' and cap w/2</li> <li>Set CIBP @ 12</li></ol></li></ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le DEF TBG STUB	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ol> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/32</li> <li>cement plug at tubing stub¥ WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk plugating 4) Shoot off 5-1/2" casing and jack of 5.</li> <li>TIH w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7.</li> <li>Restore location.</li> <li>50' / N ≠ OUT</li> </ol> </li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre <del>repen hole</del> ) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFTBG STUB above is true and complete to the best of my knowle	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ol> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/32</li> <li>cement plug at tubing stub¥ WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk plugating 4) Shoot off 5-1/2" casing and jack of 5.</li> <li>TIH w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7.</li> <li>Restore location.</li> <li>50' / N ≠ OUT</li> </ol> </li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard to but of hole until rig can pull remaining pipe. Finisl tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ol> <li>13. Describe proposed or compof starting any proposed woor recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/32</li> <li>cement plug at tubing stub WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating 4) Shoot off 5-1/2" casing and jack of 5.</li> <li>TIH w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7.</li> <li>Restore location.</li> <li>50' / N ≠ OUT</li> <li>I hereby certify that the information a grade tank has been/will be constructed or</li> </ol> </li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre <del>repen hole</del> ) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFFTBGSTUB above is true and complete to the best of my knowle closed according to NMOCD guidelines $\square$ , a general permit	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ol> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure:         <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/32</li> <li>cement plug at tubing stub¥ WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25-sk plugating 4) Shoot off 5-1/2" casing and jack of 5.</li> <li>TIH w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7.</li> <li>Restore location.</li> <li>50' / N ≠ OUT</li> </ol> </li> </ol>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre <del>repen hole</del> ) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFFTBGSTUB above is true and complete to the best of my knowle closed according to NMOCD guidelines $\square$ , a general permit	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ul> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/2.</li> <li>Cement plug at tubing stubar WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating and jack of 5.1/2" casing and jack of 7.</li> <li>Restore location.</li> <li>50' IN ≠ OUT</li> </ol> </li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cent 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate free perimeter at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFTBG5TUB above is true and complete to the best of my knowle closed according to NIOCD guidelines $\boxtimes$ , a general permit $OMULTICE_Engineer$	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel or an (attached) alternative OCD-approved plan DATE_9/13/07
<ul> <li>13. Describe proposed or compof starting any proposed woor recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/2.</li> <li>Cement plug at tubing stubak WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating and jack of 5.1/2" casing and jack of 7.1 K + 2.7/8" tubing. Spot and 25 sx plug across bottom of intermed 6.1 Cut off casing and weld plate on 5.1 K + 0.0 T</li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATUREType or print name Larry O. Miller</li> </ol></li></ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cent 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate free perimeter at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFTBG5TUB above is true and complete to the best of my knowle closed according to NIOCD guidelines $\boxtimes$ , a general permit $OMULTICE_Engineer$	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel.
<ul> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/2.</li> <li>Cement plug at tubing stubar WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating and jack of 5.1/2" casing and jack of 7.</li> <li>Restore location.</li> <li>50' IN ≠ OUT</li> </ol> </li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OF TBG STUB above is true and complete to the best of my knowle closed according to NMOCD guidelines $\boxtimes$ , a general permit $OMOCD$ TITLE_Engineer E-mail address: larrym@prid	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel cor an (attached) alternative OCD-approved plan DATE_9/13/07
<ul> <li>13. Describe proposed or compost of starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-</li> <li>Set CIBP @ 11,880' and cap w/ 3</li> <li>cement plug at tubing stubar WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating 4) Shoot off 5-1/2" casing and jack of 5) T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7) Restore location.</li> <li>50' / N ≠ OUT</li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE</li> </ol> </li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 15' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole) at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OF TBG STUB above is true and complete to the best of my knowle closed according to NMOCD guidelines $\boxtimes$ , a general permit $OMOCD$ TITLE_Engineer E-mail address: larrym@prid	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2'' casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel cor an (attached) alternative OCD-approved plan DATE_9/13/07
<ul> <li>13. Describe proposed or compof starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/ 3.</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugair 4) Shoot off 5-1/2" casing and jack 65.</li> <li>T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6. Cut off casing and weld plate on 17.</li> <li>Restore location.</li> <li>50' IN + OUT</li> </ol> </li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE.</li> <li>Type or print name Larry O. Miller For State Use Only</li> <li>APPROVED BY: Way, J.</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cent 55' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate free perimeter at top of Wolfcamp (9225'), Drinkard ( but of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le OFTBG5TUB above is true and complete to the best of my knowle closed according to NIOCD guidelines $\boxtimes$ , a general permit $OMULTICE_Engineer$	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs v (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel c or an (attached) alternative OCD-approved plan DATE
<ul> <li>13. Describe proposed or compost of starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-</li> <li>Set CIBP @ 11,880' and cap w/ 3</li> <li>cement plug at tubing stubar WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating 4) Shoot off 5-1/2" casing and jack of 5) T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6) Cut off casing and weld plate on to 7) Restore location.</li> <li>50' / N ≠ OUT</li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE</li> </ol> </li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Cut off 2-7/8" tubing above free         ag plug and POH w/ tubing.         Set casing jacks and measure stretch to estimate free	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs v (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or below contact of a liternative OCD-approved plan DATE_9/13/07
<ul> <li>13. Describe proposed or compof starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/ 3.</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugair 4) Shoot off 5-1/2" casing and jack 65.</li> <li>T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6. Cut off casing and weld plate on 17.</li> <li>Restore location.</li> <li>50' IN + OUT</li> </ol> </li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE.</li> <li>Type or print name Larry O. Miller For State Use Only</li> <li>APPROVED BY: Way, J.</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 5' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole at top of Wolfcamp (9225'), Drinkard ( pout of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le CFTBG STUB above is true and complete to the best of my knowle closed according to NOCCD guidelines [], a general permit OMDED BUICTILE_Engineer	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel or an (attached) alternative OCD-approved plan DATE_9/13/07 de-energy.com Telephone No. (918) 524-920 EU/STAFF MANAGESED 1 7 20
<ul> <li>13. Describe proposed or compof starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/ 3.</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugair 4) Shoot off 5-1/2" casing and jack 65.</li> <li>T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6. Cut off casing and weld plate on 67.</li> <li>Restore location.</li> <li>50' IN + OUT</li> </ol> </li> <li>I hereby certify that the information agrade tank has been/will be constructed or SIGNATURE.</li> <li>Type or print name Larry O. Miller For State Use Only</li> <li>APPROVED BY: Out (if any)</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 5' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole at top of Wolfcamp (9225'), Drinkard ( pout of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le CFTBG STUB above is true and complete to the best of my knowle closed according to NOCCD guidelines [], a general permit OMDED BUICTILE_Engineer	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs w (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or bel or an (attached) alternative OCD-approved plan DATE_9/13/07 de-energy.com Telephone No. (918) 524-920 EU/STAFF MANAGESED 1 7 20
<ul> <li>13. Describe proposed or compof starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/ 3.</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugair 4) Shoot off 5-1/2" casing and jack 65.</li> <li>T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6. Cut off casing and weld plate on 17.</li> <li>Restore location.</li> <li>50' IN + OUT</li> </ol> </li> <li>I hereby certify that the information is grade tank has been/will be constructed or SIGNATURE.</li> <li>Type or print name Larry O. Miller For State Use Only</li> <li>APPROVED BY: Way, J.</li> </ul>	Ieted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Cut off 2-7/8" tubing above free         ag plug and POH w/ tubing.         Set casing jacks and measure stretch to estimate free         -spenhole) at top of Wolfcamp (9225'), Drinkard (9225'), Drinkard (9205') in and 50'out of stub. Spot remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le         OF TBG STUB         above is true and complete to the best of my knowled closed according to NMOCD guidelines ⊠, a general permit         OMALL CONSERVATION         TITLE_Engineer         THE OIL CONSERVATION         BE NOTIFIED 24 HOURG	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs v (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or below to an (attached) alternative OCD-approved plan DATE 9/13/07
<ul> <li>13. Describe proposed or compof starting any proposed we or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/3.</li> <li>cement plug at tubing stub<b>X</b> WOC, t</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugating 4) Shoot off 5-1/2" casing and jack of 5.</li> <li>TIH w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed.</li> <li>Cut off casing and weld plate on the formation and the information of the start of the start of the information of the start of the information of the start of the start</li></ol></li></ul>	Ieted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions:         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cerr         7/8" tubing. Cut off 2-7/8" tubing above free         ag plug and POH w/ tubing.         Set casing jacks and measure stretch to estimate free         -spenhole) at top of Wolfcamp (9225'), Drinkard (9225'), Drinkard (9205') in and 50'out of stub. Spot remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le         OF TBG STUB         above is true and complete to the best of my knowled closed according to NMOCD guidelines ⊠, a general permit         OMALL CONSERVATION         TITLE_Engineer         THE OIL CONSERVATION         BE NOTIFIED 24 HOURG	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs v (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or below to an (attached) alternative OCD-approved plan DATE 9/13/07
<ul> <li>13. Describe proposed or compof starting any proposed wo or recompletion.</li> <li>Proposed Plugging Procedure: <ol> <li>RUPU. Calculate freepoint of 2-2.</li> <li>Set CIBP @ 11,880' and cap w/ 3.</li> <li>Weld lift sub on 5-1/2" casing</li> <li>be placed in casing (or 25 sk plugair 4) Shoot off 5-1/2" casing and jack 65.</li> <li>T1H w/ 2-7/8" tubing. Spot and 25 sx plug across bottom of intermed 6. Cut off casing and weld plate on 67.</li> <li>Restore location.</li> <li>50' IN + OUT</li> </ol> </li> <li>I hereby certify that the information agrade tank has been/will be constructed or SIGNATURE.</li> <li>Type or print name Larry O. Miller For State Use Only</li> <li>APPROVED BY: Out (if any)</li> </ul>	leted operations. (Clearly state all pertinent details, rk). SEE RULE 1103. For Multiple Completions: 7/8" tubing. Tag CIBP @ 12,150'. Spot 35' cen 5' cement plug. Cut off 2-7/8" tubing above free ag plug and POH w/ tubing. Set casing jacks and measure stretch to estimate fre per hole at top of Wolfcamp (9225'), Drinkard ( pout of hole until rig can pull remaining pipe. Finish tag plug 50' in and 50'out of stub. Spot remaining liate pipe (4307'). Circulate cement from 439' (5 top. Set standard P&A marker 4' above ground le CFTBG STUB above is true and complete to the best of my knowle closed according to NOCCD guidelines [], a general permit OMDED BUICTILE_Engineer	Attach wellbore diagram of proposed completent plug w/ dump bailer. WOC. point. Circulate hole w/ 9.5 ppg mud. Spot epoint. Depending on freepoint, 100' plugs v (6164'), Queen (3704), and Salt (2164'). n pulling 5-1/2" casing. plugs at formation tops as described above, p 0' below shoe of surface pipe) to surface. vel. edge and belief. I further certify that any pit or below to an (attached) alternative OCD-approved plan DATE 9/13/07 de-energy.com Telephone No. (918) 524-920 EUSTAIT MANAGES DATE SEP 1 7 20

-

í.



ممسو