

GENERALIZED STRUCTURAL CROSS SECTION
Surface to Basement

Southeastern Eddy County, New Mexico

