

09-Mar-15

Well Inspection History

API Number: **30-045-27007-00-00**

Well Name & No.: **WILD SWEDE**

Operator: **GLEN A DEVILBISS,**


District: **AZTEC**

County Name: **SAN JUAN**

Field: **WILD SWEDE**

Legal: **S: 6 T: 30N R: 15W**

Well Type: **OIL (PRODUCING)**



Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
10/22/2014	Routine/Periodic	Normal Routine Activity	iJDD14295358		323		
		Two fiberglass tanks, three vehicles and the remains of a mobile home on location. Pump jack as been removed pump rods are still in the well. Fence around the production tank is falling down. There are puddles of rain water near the "Dump truck" and garbage is scattered across the location.					
8/26/2014	Routine/Periodic	Normal Routine Activity	iJK142383515		325		
		No noticable change to location condition. Some standing stormwater on location.					
4/17/2014	Routine/Periodic	Normal Routine Activity	iJK141074347		325		
		Still no noticeable change in location conditions.					
3/28/2014	Routine/Periodic	Normal Routine Activity	iJK140873879		325		
		Still no noticeable change in location conditions. Still several globs of impacted-soils on location. 2 poly containers referenced in last inspection are no longer on site. No standing fluid phase hydrocarbons. Still no well sign on location and moderate amount of refuse on northern end of location. Fiberglass tank set on top of part of the tank containment is starting to deteriorate and crack.					
1/3/2014	Routine/Periodic	Normal Routine Activity	iJK140033749		325		
		Still no noticeable change in location conditions. Still several globs of impacted soils on location. 2 poly containers on site, empty. No standing fluid phase hydrocarbons, but several areas ponding storm water that is frozen. Still no well sign on location and moderate amount of refuse on northern end of location.					
11/1/2013	Routine/Periodic	Normal Routine Activity	iJK133053412		325		
		Still no noticeable change in location conditions. Still several globs of impacted soils on location. 2 poly containers on site, empty. No standing fluid phase hydrocarbons, but several areas ponding storm water. Still no well sign on location and moderate amount of refuse on northern end of location.					
9/18/2013	Routine/Periodic	Normal Routine Activity	iJK132613737		325		
		Little change in location conditions. Tank gangway mentioned on west side of location in prior inspections is gone, still several globs of impacted soils on location. 2 poly containers on site, empty. No standing fluid phase hydrocarbons, but several areas ponding storm water. Still no well sign on location and moderate amount of refuse on northern end of location.					
7/17/2013	Routine/Periodic	Normal Routine Activity	iJK131984204		325		
		Onsite to check on condition of site, No noticable change to location.					
4/22/2013	Routine/Periodic	Normal Routine Activity	iJK131124274		325		
		Onsite to check up on location. Still no well sign. Pumpjack has been removed along with some of the tanks and junk on location. Globs of parafin and impacted soils in several places on site, with <1 gal puddles in two places. Segments of poly line along location edge and arroyo side on NW corner of location. Burnt car frame on location has been flipped over from prior visit, old tires down bank on northside of location near old Blue truck. Remenants of old trailer still on site along with truck holding impacted soils. Tank berm appears to have been untouched from last visit other than the oil/parafin staining on one of the tank berms fence posts that has been laying on the ground. Bits of tubing and sucker rod in various areas around location, cement slabs from pump jack still in place with another on the SW and SE corners of location. Portion tank walk away mangled and on ground on west side of location where one of the old tanks once was, portion of tank hatch east of it. Overall, location in poorer condition than last visit.					
11/13/2012	Routine/Periodic	Normal Routine Activity	iJK123184707		325		
		No real change in location condition from prior inspections.					
7/10/2012	Routine/Periodic	Normal Routine Activity	iJK121934018		325		
		No change to location, see last inspection for more detail.					
5/14/2012	Routine/Periodic	Normal Routine Activity	iJK121353519		325		
		Only changes from last inspection is that the fence on the south and west side of the tank battery is opened and the southern fiberglass tank has been pulled onto the berm through the hole in the south side of fence. Staining on ground around tanks and well head. Fairly fresh looking heavy crude pooled on east side of metal storage tank.					
10/21/2011	Routine/Periodic	Normal Routine Activity	iMPK1129456		312		
		truck moved - windshield broken out engine has been broken in to - fencing down around open top polyurethane tanks - trailer has collapsed - contaminated soil still in truck					
9/29/2011	Routine/Periodic	Normal Routine Activity	iJK112724303		325		
		Unable to locate well sign. Well not in production. Several disconnected steel tanks along with other refuse on location. Production tank shows signs of leak on line area to the fiberglass tanks. Both fiberglass tanks dry with salts in bottom and lumps of dried grease or crude. Berm around well head stained.					
5/23/2011	Routine/Periodic	Normal Routine Activity	iJDD11143408		323		
		Inopperible pump jack attached to well. Delapitated mobile home on location. Another inopperible pump jack on location. Broke down construction equipment on location. Hose going from production tank to a fiber glass above ground tank. Both fiber glass above ground tanks are full of salt. Location over run with ankle to waist high weeds. Tractor trailers, dump truck and related equipment is on location.					
8/19/2010	Routine/Periodic	Normal Routine Activity	iMPK1023137		312		
		pretty much the same there is a hose running from the production tank to an open top tank to the right - the valve from the production tank has had a leak oil staning and some standing near valve with a path to the open top tank					
5/4/2010	Routine/Periodic	Normal Routine Activity	iMPK1012456		312		
		all the same - talked with Richard Baldwin later in the day and he said they had pumped the well in January but only got water. Negotiations have stopped with Santa Fe on the transfer of this well. Richard and wife have previously been talking with Jane Prouty.					

5/25/2001	Routine/Periodic	Normal Routine Activity	iWBM0114533		308	
	No Well Sign. Junk still being stored on location. Hole dug near well head has oil in it.					
5/24/2001	Routine/Periodic	Normal Routine Activity	IEHV0114462		307	
	RESPOND TO CALL FROM CHARLIE PERRIN, STUFFING BOX LEAKING, GLEN DEVELBIS ARRIVE SAME TIME WILL CLEAN UP LESS THAN 3 GAL OIL TOP OF RAIN WATER.					
1/18/2001	Routine/Periodic	Normal Routine Activity	iWBM0101837		308	
	Well is SI. Well sign needs to be replaced, hard to read.					
12/19/2000	Routine/Periodic	Normal Routine Activity	IEHV0035455		307	
	OKAY LOTS JUNK ON LOCATION.					
4/11/2000	Routine/Periodic	Normal Routine Activity	IEHV0000947		307	
	INSPECT CLEANUP OF OIL SPILL, WAS EXCAVATED, AND BERM AROUND TANKS BEEN REBUILT.					
2/28/2000	Routine/Periodic	Request/Complaint	IDGF0000021	4/15/2000	304	109
	Wild Swede #1 needs to remediate spills at the well head by excavation. The berm needs to be rebuilt at the earthen pit west of well head to prevent hydrocarbon from entering the pit. The location has 4 extra production tanks, extra pumjack, truck and float with house trailer loaded on the float, two horizontal tanks, there are several bases on location. The inspection was in response to complaint from the landowner about material stored on location.					
10/13/1999	Routine/Periodic		iWBM0002415		308	
	Stuffing box leaking - 1 bbl of oil on ground. Old stained soil around pumping unit from old leaks.					

Total Inspections Performed: 46







