

07-Apr-08

## Well Inspection History

API Number: 30-045-25092-00-00

Well Name &amp; No.: DAVIE

Operator: NORTHSTAR OIL &amp; GAS,

District: AZTEC

County Name: SAN JUAN

Field: DAVIE

Legal: S: 2 T: 29N R: 15W

Well Type: OIL (PRODUCING)

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
3/5/2008	Plugged Well Surface Restor	Normal Routine Activity	iKGR0806626		313		
	Location does not appear to be re-seeded. Pipeline riser located at southwest corner of location. Fence posts and power pole remain on location at land owner's request. Took photos of location.						
12/3/2007	Routine/Periodic	Normal Routine Activity	iKGR0802858		313		
	Location does not appear to be seeded. Pipeline riser at Southeast corner of location. All information on p&a marker is correct. Location has been leveled. Fence posts still standing around perimeter of location. Electric pole with box on it still standing at Southwest corner of location.						
12/3/2007	Routine/Periodic	Normal Routine Activity	iKGR0802849		313		
	Location does not appear to be seeded. Pipeline riser at Southeast corner of location. All information on p&a marker is correct. Location has been leveled. Fence posts still standing around perimeter of location. Electric pole with box on it still standing at Southwest corner of location.						
10/10/2007	Routine/Periodic	Normal Routine Activity	iKGR0728340		313		
	Oil tank at Northwest corner of location. Power Pole at southwest corner of location. Pipeline riser at Southeast corner of location. Fence posts around perimeter of location. Some chain link fence still standing at Northwest corner of location near oil tank. Took photos of area.						
9/6/2007	Plugging Witnessed	Normal Routine Activity	IEHV07250426		307		
	witness plugging.						
9/5/2007	Plugging Witnessed	Normal Routine Activity	IEHV07250417		307		
	witness plugging by A-plus rig seven. Set cr at 4207 test csg to 800 psi, test good. Spot 35 sacks typ 3 cement top cr 3691. sdfd.						
9/4/2007	Routine/Periodic	Normal Routine Activity	iKGR0724750		313		
	A-Plus rig number 7 on location. Will rig up tomorrow. Well head valve will not open.						
5/23/2007	Routine/Periodic	Normal Routine Activity	IEHV07143562		307		
	Met with Bill Randall with A-plus to help locate and identify. He was flagging to plug and abandon. @ inch valve on top of 4.5 casing appears to have cement in it?						
10/27/2005	Routine/Periodic	Normal Routine Activity	IMPK0530043		312		
	took pictures -could only find one anchor - gate at entrance to field is wired up to the point that it cannot be opened - the fence is down west of the gate area.						
5/4/2005	Routine/Periodic	Normal Routine Activity	IEHV05124586		307		
	took pictures, abandoned.						
5/2/2005	Routine/Periodic	Normal Routine Activity	IEHV05122598		307		
	looks abandoned, DENNY Foust and myself went to well, after returning to office, met with Charlie Perrin, unable to contact operator recording said # has been disconnected.						
2/6/2004	Routine/Periodic	Normal Routine Activity	IWBM0403755		308		
	Appears abandoned.						
5/16/2002	Routine/Periodic	Normal Routine Activity	IEHV02136524		307		
	CONTACTED JIM CORBETT, OPERATOR SAID WOULD MAKE SIGN AND SAID HE WAS GOING TO PLUG WELL OR SELL IT.						
5/15/2002	Routine/Periodic	Normal Routine Activity	IEHV02135399		307		
	No Well Sign. Appears abandoned.						
3/11/1999	Routine/Periodic		IWBM0000239		308		
	Appears abandoned.						

Total Inspections Performed: 15

Before the OCC  
Case 13920  
Northstar Oil & Gas  
OCD Ex. No. 8