

14-Mar-08

## Well Inspection History

API Number: **30-015-20088-00-00** Well Name & No.: **RESLER YATES STATE**  
Operator: **SANDLOTT ENERGY (JACKIE BREWER D)** District: **ARTESIA** County Name: **EDDY**  
Field: **RESLER YATES STATE** Legal: **S: 32 T: 18S R: 28E**  
Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/16/2007	Routine/Periodic	Normal Routine Activity	iMLB07197424		211		
Partial well sign laying on ground. Power switch is off. Contamination at well head area and West of pumping unit, as noted in 2006 inspection, has had no change. Several patches on metal flowline.							
7/5/2006	File and Compliance Review	Normal Routine Activity	iPCH0618638		210		
No electrical power hooked to motor on pumping unit. Broken well sign on ground, contamination around wellhead and csg. Contamination at flow line West side of location							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242509		211		
No Pumping Unit or production equipment. No compliant well sign. Contaminated area along flowline on West side of location.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423339		209		
No Pumping Unit. Last reported production April 2003. Area contaminated. No well sign.							
10/19/1999	Routine/Periodic	Status Check	iELG0003120		207		
A-OK. All Equipment and Location in Good Shape.							

**Total Inspections Performed: 5**

**Jackie Brewer D/B/A  
Sandlott Energy  
Case 14074  
OCD Exhibit No. 9**