

14-Mar-08

Well Inspection History

API Number: **30-015-26134-00-00**

Well Name & No.: **RESLER YATES STATE**

Operator: **SANDLOTT ENERGY (JACKIE BREWER D**

District: **ARTESIA**

County Name: **EDDY**

Field: **RESLER YATES STATE**

Legal: **S: 32 T: 18S R: 28E**

Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
7/24/2007	Routine/Periodic	Normal Routine Activity	iMLB07205435		211		
No belts or sheaves on pumping unit rendering it inoperable. Contamination and standing oil around tanks at tank battery on West side of well site. No well sign at well site or at battery.							
7/5/2006	File and Compliance Review	Normal Routine Activity	iPCH0618640		210		
No Motor on Pumping Unit. Contamination around wellhead and tanks							
10/20/2005	Compliance Verification	Normal Routine Activity	iCLB05293456		212		
Took samples along north side of tanks. Sample 1: 32.70595N 104.19419W 6 inches Sample 2: 32.70582N 104.18414W 6 inches Sample 3: 32.70591N 104.19406W 6 inches							
Tanks: 1: 32.70610N 104.19416W 2: 32.70605N 104.19416W 3: 32.70595N 104.19417W 4: 32.70590N 104.19418W 5: 32.70589N 104.18410W GB1: 32.70593N 104.19408W GB2: 32.70597N 104.19411W							
8/30/2005	Routine/Periodic	Normal Routine Activity	iMLB05242532		211		
No Motor on Pumping Unit. No well sign. No indication of recent activity at well site. Tank battery at this well is heavily contaminated. Ground at two storage vessels are oil saturated indicating probable leaks in tank bottoms. One tank is collapsed.							
8/20/2004	Routine/Periodic	Normal Routine Activity	iGEG0423338		209		
No Motor on Pumping Unit. Area contaminated. No well sign.							
9/17/2002	Routine/Periodic	Normal Routine Activity	iMCS0234365		205		
Inspected spill on injection line running north of tank battery. Letter sent to operator. Request for C-141.							
9/18/2001	Routine/Periodic	Normal Routine Activity	iMCS0126155		205		
RECHECKED TANK BATTERY FOR STATUS OF SPILL REMEDIATION. OPERATOR HAS PICKED UP STANDING OIL FROM SPILL WEST OF TANK BATTERY. SPILL AREA HAS BEEN BACKDRAGGED USING A BACKHOE. ADDITION WORK AROUND STOCK TANKS NEEDED.							
9/11/2001	Routine/Periodic	Request/Complaint	iMCS0125439	10/11/2001	205	Y	
UNREPORTED OIL SPILL AT TANK BATTERY. VIOLATION RULE 116.							
10/19/1999	Routine/Periodic	Status Check	iELG0003128		207		
A-OK. All Equipment and Location in Good Shape. B/T							

Total Inspections Performed: 9

Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 11