

28-Aug-08

## Well Inspection History

API Number: 30-015-26895-00-00

Well Name & No.: LEVERS A STATE

Operator: SANDLOTT ENERGY (JACKIE BREWER DB District: ARTESIA County Name: EDDY

Field: LEVERS A STATE

Legal: S: 8 T: 18S R: 28E

Well Type: OIL (PRODUCING)

*Jackie Brewer D/B/A  
Sandlott Energy  
De Novo Case 14074  
OCD Exhibit No. 6*

Lever A State #002

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
8/4/2008	Routine/Periodic	Normal Routine Activity	iGEG0821740		209		
Well is not pumping. Took photos.							
10/3/2007	Routine/Periodic	Normal Routine Activity	iMLB07276604		211		
Inspected site with OCD reps, Daniel Sanchez and Sonny Swazo. Increased oil release was observed at base of separator, base of East tank, and small ongoing produced water release at West tank. Well was pumping at time of inspection.							
7/20/2007	Routine/Periodic	Normal Routine Activity	iMLB07201438		211		
No well sign. Contamination at well head area. Power switch is off. No indication of recent activity at well site. Tank battery situated approx 100 yards South of well site still has collapsed tank on location. No indication of any clean up having been done from releases that have occurred at the battery site. Fluids are being pumped into West tank. (Can hear fluids moving through poly flow line that is plumbed into West tank)							
10/20/2005	Compliance Verification	Normal Routine Activity	iCLB05293352		212		
Took samples along south side of tanks. Sample 1: 32.76692N 104.19706W 3-6 inches Sample 2: 32.76694N 104.19693W 3-6 inches Sample 3: 32.76695N 104.19683W 3-6 inches							
Tanks: 1: 32.76693N 104.19694W 2: 32.76693N 104.19690W 3: 32.76690N 104.19685W (Original Location) Gun barrel: 32.76689N 104.19684W							
Tank 3 has been moved and is lying on southeast side of location between roads to well area.							
8/29/2005	Routine/Periodic	Normal Routine Activity	iMLB05241510		211		
No well sign at well site. No indication pumpjack has had recent operation. Contamination at well head area. Tank battery South of this well has collapsed tanks that have released produced fluids. No action taken by operator to bring well or tank battery area into compliance.							
7/22/2005	Compliance Verification	Normal Routine Activity	iCLB05203327		212		
No Action Taken To bring Well into Compliance. Oil and produced liquids standing in pools around tank battery, oil and produced liquids have run down road approximately 100 yards towards wellhead. Heavy chloride staining on road west of tank battery.							
5/9/2005	Routine/Periodic	Normal Routine Activity	iMLB05129491		211	Y	109
Tank battery South of this well is heavily contaminated. Collapsed tanks and overturned vessels at site. Storage tank on West end has an active produced water leak. Notified operator to fix leak. Chloride impacted soils are to be properly remediated/hailed to disposal facility.							
8/19/2004	Routine/Periodic	Normal Routine Activity	iGEG0423252		209		
No Action Taken To bring Well into Compliance. Electricity is off.							
4/8/2004	Compliance Verification	Normal Routine Activity	iMLB04099439		211	Y	
No Action Taken To bring Well into Compliance. No well sign. Area at well head is heavily contaminated. Last production reported was 7/2002. Well is now in violation of Rule 201.							
10/9/2003	Compliance Verification	Normal Routine Activity	iMLB03282408		211		
No action taken on pollution and contamination violation or on no well sign violation. Both violations opened in Jan. 2003.							
4/16/2003	Compliance Verification	Normal Routine Activity	iMLB03106457		211		
No action taken on violations from 1/03.							
2/24/2003	Compliance Verification	Normal Routine Activity	iGEG0305538		209		
No action taken on previous violations.							
1/23/2003	Routine/Periodic	Normal Routine Activity	iMLB03023569		211	Y	
Production indicated in 7/2002. Leaks/spills have caused large area of contamination at well head area. Violation of Rule 13 and Rule 116.							
1/22/2003	Routine/Periodic	Normal Routine Activity	iMLB03022522		211	Y	
Bridle line for pumpjack is disconnected. Large area of contamination and standing oil at well head. Well sign illegible, does not list operator and is not mounted. Well sign is in violation of Rule 103.							
10/18/1999	Routine/Periodic	Status Check	iELG0002793		207		
A-OK. All Equipment and Location in Good Shape.							

**Total Inspections Performed: 15**