


R14W



Examiner _____
Case No. 12098
EXHIBIT NO. 2

CONTOUR INTERVAL: 25 Feet



Cross Timbers Oil Company

UTE DOME FIELD

San Juan County, New Mexico

STRUCTURE: Top of Dakota

November, 1998

GKB/MSV

Down-to-North Fault

Down-to-South Fault

Active Dakota Producing Well

NEW MEXICO
OIL CONSERVATION DIVISION

_____ EXHIBIT 2 _____

CASE NO. _____