


R14W



Examiner 12098
Case No. 4
EXHIBIT NO. 4

-  Down-to-North Fault
-  Down-to-South Fault
-  Active Dakota Producing Well

 Cross Timbers Oil Company	
UTE DOME FIELD San Juan County, New Mexico	
STRUCTURE: Top of Dakota	
November, 1998	GKB/MSV

NEW MEXICO
WILDLIFE CONSERVATION DIVISION

EXHIBIT 4

CASE NO. _____