
BLACK DIAMOND COM 20 #1


HORIZONTAL GALLUP SE/SW Sec. 20, T30N-R15W San Juan Co., N.M.

TYPICAL VERTICAL WELL

HORIZONTAL WELL

IN MARGINAL AREAS THE HORI-ZONTAL TECHNOLOGY IS NEEDED TO RECOVER RESERVES THAT WOULD NOT BE RECOVERED BY A VERTICAL WELLBORE.





ESTIMATED COST - \$ 850,000 - 1,400,000

ESTIMATED COST - \$ 500,000 - 600,000