


**Before The Oil Conservation Division
 Santa Fe, New Mexico**
 Case No.'s 10807, 10808, 10809
 Exhibit No. 1
 Submitted by: Kinlaw Oil Corporation
 Hearing Date: September 24, 1993

KINLAW OIL CORPORATION
South Denton (Devonian) Field
 Lea County, New Mexico
 Kinlaw Leasehold
 Scale: 1" = 2,000'




*Devon
Sulfur water
carbonate*

**Before The Oil Conservation Division
Santa Fe, New Mexico**

Case No.'s 10807, 10808, 10809
 Exhibit No. 2
 Submitted by: Kinlaw Oil Corporation
 Hearing Date: September 24, 1993

KINLAW OIL CORPORATION

South Denton (Devonian) Field
 Lea County, New Mexico
 Structure Map
 Top of the Devonian
 C I : 100' Scale: 1" = 2,000'



Before The Oil Conservation Division
Santa Fe, New Mexico

Case No.'s 10807, 10808, 10809

Exhibit No. 3

Submitted by: Kinlaw Oil Corporation

Hearing Date: September 24, 1993

KINLAW OIL CORPORATION


South Denton (Devonian) Field

Lea County, New Mexico

Net Pay Isopach

(Feet above original oil/water contact)

C I : 100' Scale: 1" = 2,000'



**Before The Oil Conservation Division
Santa Fe, New Mexico**


Case No.'s 10807, 10808, 10809
 Exhibit No. 4
 Submitted by: Kinlaw Oil Corporation
 Hearing Date: September 24, 1993

KINLAW OIL CORPORATION

South Denton (Devonian) Field
 Lea County, New Mexico

Cumulative Production Map
 Scale: 1" = 2,000'

Plugs	
①	Surface — 10 SX
②	359' — 150 SX
③	2,275' — 50 SX
④	3,100' — 50 SX
⑤	5,050' — 75 SX
⑥	8,375' — 50 SX
⑦	11,051' — 50 SX
⑧	12,850' — CIBP + 6 SX



12915' KOP
 12878' KOP
 12915' KOP
 SDB*
 12958' section 3
 13110'

**Before The Oil Conservation Division
 Santa Fe, New Mexico**
 Case No.'s 10807, 10808, 10809
 Exhibit No. 5
 Submitted by: Kinlaw Oil Corporation
 Hearing Date: September 24, 1993

KINLAW OIL CORPORATION
South Denton (Devonian) Field
 Lea County, New Mexico
 Re-entry Wellbore Diagram
 Huber - State #1