Form 3160-5 (June 2015) UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD-ARTESIA REC'D: 8/14/2020 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC065431			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2				 If Unit or CA/Agreement, Name and/or No. 891000326X 				
1. Type of Well ☐ Gas Well ☐ Other					8. Well Name and No. BIG EDDY UNIT 5E HAN SOLO 105H			
2. Name of Operator XTO PERMIAN OPERATING LLC E-Mail: kelly_kardos@xtoenergy.com					9. API Well No. 30-015-46831-00-X1			
3a. Address 6401 HOLIDAY HILL ROA MIDLAND, TX 79707			10. Field and Pool or WILDCAT - BO					
4. Location of Well (Footage, Se		11. County of			r Parish, State			
Sec 27 T20S R31E SWN 32.545815 N Lat, 103.854		EDDY COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION		TYPE OF ACTION						
☑ Notice of Intent	□ Acidize	Dee	epen	Product	ion (Start/Resume)		ater Shut-Off	
□ Subsequent Report	□ Alter Casing	-	Hydraulic Fracturing		□ Reclamation		U Well Integrity	
					omplete 🛛 Oth Chang		ther nge to Original A	
Final Abandonment Notic	ce Change Plans		g and Abandon g Back	 Temporarily Abandon Water Disposal 		PD		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. XTO requests the option to cement the surface and intermediate casing strings offline for the below								
BIG EDDY UNIT 5E HAN SOLO 105H 30-015-46831 BIG EDDY UNIT 5E HAN SOLO 114H 30-015-46830 BIG EDDY UNIT 5E HAN SOLO 102H 30-015-46833								
Attachments: Offline Cementing Procedure								
) Accepted for Re	Accepted for Record 8/17/2020 - JAG					
14. I hereby certify that the foregoing is true and correct. Electronic Submission #520198 verified by the BLM Well Information System For XTO PERMIAN OPERATING LLC, sent to the Carlsbad Committed to AFMSS for processing by PRISCILLA PEREZ on 06/25/2020 (20PP3258SE)								
Name(Printed/Typed) KELLY KARDOS			Title REGULATORY COORDINATOR					
Signature (Electronic Submission)			Date 06/25/2020					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
			TitlePETROLEUM ENGINEER Date 08/11/2020					
Approved By_ALLISON MORENCY			TitlePETROLEUM ENGINEER Date 08/11/2020 Office Carlsbad Date 08/11/2020					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								
(Instructions on page 2) ** BLM F	REVISED ** BLM REVISE	D ** BLM R	EVISED ** BLN) ** BLM REVISE	D **		

Revisions to Operator-Submitted EC Data for Sundry Notice #520198

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	APDCH NOI	APDCH NOI
Lease:	NMLC065431	NMLC065431
Agreement:	NMNM68294X	891000326X (NMNM68294X)
Operator:	XTO PERMIAN OPERATING, LLC 6401 HOLIDAY HILL RD BLDG 5 MIDLAND, TX 79707 Ph: 432-620-4374	XTO PERMIAN OPERATING LLC 6401 HOLIDAY HILL ROAD BLDG 5 MIDLAND, TX 79707 Ph: 432.683 2277
Admin Contact:	KELLY KARDOS REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com Ph: 432-620-4374	KELLY KARDOS REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com Ph: 432-620-4374
Tech Contact:	KELLY KARDOS REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com Ph: 432-620-4374	KELLY KARDOS REGULATORY COORDINATOR E-Mail: kelly_kardos@xtoenergy.com Ph: 432-620-4374
Location: State: County:	NM EDDY	NM EDDY
Field/Pool:	WILDCAT BONE SPRING	WILDCAT - BONE SPRING
Well/Facility:	BIG EDDY UNIT 5E HAN SOLO 105H Sec 27 T20S R31E Mer NMP SWNE 2145FNL 1885FEL	BIG EDDY UNIT 5E HAN SOLO 105H Sec 27 T20S R31E SWNE 2145FNL 1885FEL 32.545815 N Lat, 103.854523 W Lon

XTO requests the option to cement the surface and intermediate casing strings offline as a prudent batch drilling efficiency of acreage development.

1. Cement Program

No changes to the cement program will take place for offline cementing.


2. Offline Cementing Procedure

The operational sequence will be as follows. If a well control event occurs, the BLM will be contacted for approval prior to conducting offline cementing operations.

- 1. Run casing as per normal operations. While running casing, conduct negative pressure test and confirm integrity of the float equipment (float collar and shoe)
- 2. Land casing with mandrel
- 3. Fill pipe with kill weight fluid, do not circulate through floats and confirm well is static
- 4. Set annular packoff shown below and pressure test to confirm integrity of the seal. Pressure ratings of wellhead components and valves is 5,000 psi.
- 5. After confirmation of both annular barriers and internal barriers, nipple down BOP and install cap flange.
 - a. If any barrier fails to test, the BOP stack will not be nippled down until after the cement job is completed with cement 500ft above the highest formation capable of flow with kill weight mud above or after it has achieved 50-psi compressive strength if kill weight fluid cannot be verified.




Annular packoff with both external and internal seals



Wellhead diagram during skidding operations

- 6. Skid rig to next well on pad.
- 7. Confirm well is static before removing cap flange, flange will not be removed and offline cementing operations will not commence until well is under control. If well is not static, casing outlet valves will provide access to both the casing ID and annulus. Rig or third party pump truck will kill well prior to cementing or nippling up for further remediation.
 - a. Well Control Plan
 - i. The Drillers Method will be the primary well control method to regain control of the wellbore prior to cementing, if wellbore conditions do not permit the drillers method other methods of well control may be used
 - ii. Rig pumps or a 3rd party pump will be tied into the upper casing valve to pump down the casing ID
 - iii. A high pressure return line will be rigged up to lower casing valve and run to choke manifold to control annular pressure
 - iv. Once influx is circulated out of the hole, kill weight mud will be circulated
 - v. Well will be confirmed static
 - vi. Once confirmed static, cap flange will be removed to allow for offline cementing operations to commence
- 8. Install offline cement tool
- 9. Rig up cement equipment



Wellhead diagram during offline cementing operations

- 10. Circulate bottoms up with cement truck
 - a. If gas is present on bottoms up, well will be shut in and returns rerouted through gas buster to handle entrained gas
 - b. Max anticipated time before circulating with cement truck is 6 hrs
- 11. Perform cement job taking returns from the annulus wellhead valve
- 12. Confirm well is static and floats are holding after cement job
- 13. Remove cement equipment, offline cement tools and install night cap with pressure gauge for monitoring.