
Submit 1 Copy To Appropriate District Office		11/30/2020 - NMOCD Form C-103					
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013					
1625 N. French Dr., Hobbs, NM 88240 District II = (575) 748-1283		WELL API NO. 30-015-33084					
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease					
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE S FEE					
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM	,	o. Blate on at Gus Lease No.					
87505							
1	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name					
	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	Loving 1 State					
PROPOSALS.)	non roll blain (rolling to the form	8. Well Number #4					
	as Well 🛛 Other						
2. Name of Operator		9. OGRID Number					
COG Operating, LLC		229137					
3. Address of Operator	2004.0	10. Pool name or Wildcat					
2208 W. Main Street Artesia, NM 8	88210	Black River Morrow					
4. Well Location							
Unit Letter J: 1	980feet from theSline and19	80 feet from the <u>E</u> line					
Section 1	Township 24S Range 27E	NMPM County Eddy					
	11. Elevation (Show whether DR, RKB, RT, GR, etc.						
	3102' GR						
12. Check An	propriate Box to Indicate Nature of Notice	Report or Other Data					
12. Chock rip	propriate Box to majoute retail of rection	, resport of Other Data					
NOTICE OF INT	ENTION TO: SUE	BSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🛛 📗 REMEDIAL WOR	RK ALTERING CASING					
TEMPORARILY ABANDON	CHANGE PLANS 🔲 COMMENCE DF	RILLING OPNS. P AND A					
PULL OR ALTER CASING	MULTIPLE COMPL ☐ CASING/CEMEN	NT JOB					
DOWNHOLE COMMINGLE	No	tify OCD 24 hrs. prior to any work					
CLOSED-LOOP SYSTEM		tify OCD 24 hrs. prior to any work					
OTHER:	☐ OTHER: doi						
	ed operations. (Clearly state all pertinent details, a						
). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of					
proposed completion or recon	ipletion.						
L Sat CIPD @ 11200' Cira	hole w/ MLF. Pressure test csg. Spot 25 sx cmt @	11200 11200 WOC & Tag					
	2. Perf& sqz 30 :xcmt @ 10600-10495'. WOC & TAG (7" Shoe) 2a - Perf & sqz 30 sx cmt at 9550' - 9450' WOC & tag - T V						
3. Perf& sqz 30 ixcmt @ 5800-570 0'. 3800'-3700' WOC & tag							
	60-2260'. WOC & TAG (9 5/8" Shoe)						
 Perf& sqz 30 ixcmt @ 72. 	5-625'. WOC & TAG (13 3/8" Shoe) Perf @ 625	<mark>'</mark>)					
Perf& sqz 30 sx @ 200' te	o surface.						
7. Cut off well head, verify	cmt to surface, Weld on Dry Hole Marker.						
	•						
****SEE ATTACHED COA	MIIST P	BE PLUGGED BY 12/8/2021					
SEL ATTACHED COA	WOST	DE PEUGGED DT 12/0/2021					
Spud Date:	Rig Release Date:						
	10. c						
I hereby certify that the incormation ab	eve is true and complete to the best of my knowled	ge and belief.					
*))		-					
a la lata							
SIGNATURE	TITLE: Regulatory Technician	DATE: 11/30/2020					
Type or print name: Delilah Flores	E-mail address: dflores2@concho.com	PHONE: 575-748-6946					
For State Use Only							
APPROVED BY:	- TITLE St. 11701.	nager DATE 12/8/2020					
APPROVED BY:	TITLE Staff Ma	nager DATE 12/0/2020					
Conditions of Approval (if any):		•					




WELL HAME:		Loving 1 State S1			PIELO:	Loving BE		LARGE	Q37Q			
STATE:		NM			COUNTY:	Easty		LOCATION	1907 FSLA 190	O' FEL Sec. 1-249-	27E	
LPI NO:		30-015-33064 EPUD DATE: 625-04					FORMATION: Alum					
itb:		13072			PRITO:	13066		BLEVATION:	3103 GIL		_	
			PIPE RECORD	,					CEMENT & HO	A DATA		
CBO	00	DAADE	THE	WIFT	TOP	8738	#JTS	94T 84ZE	OEFTH	SX	WL.	100
Bull	13.378	1440	LTAC	46.00#	ø	579	14	17.900°		520		8wf
	1	1	1	l .	ı	l			l			l
Seringe	1027	.85	LTC	36 00#	0	2310	53	12,250"	l	1108		But
	l	1	l	l	l	į .			1			l
leter	7.000*	HCP-110	LTAC	21 008		10548	251	6.760*	1	370		-8600
•••	,	'			-		1	1	ľ	""	ļ	
Prod	4.500"	P110	LTAC	11,000	۰	12670	321	61/8	l	280	ł	10385
The	2.37€	Neg	a-d EUE	4 708	0	11315	267	1	l	l		
omarks:								CAPACITIES		(6440)	(8564)	(cill)
7/84:	Frac Morrow parks (12)	F12-13884) or725006 Bases	o. 211 tere CO2					TBG: 2375 to 4	9	00387	258 65	.02171
	Severand out. Let 80	OF sand in cog. Cleaned out	wheat the					C80:45 In. 11.8	1	.01550	8434	.00720
r18/84:		ene (12512-16') out cag to s	_									
0000A:	Closed sharing show	, , ,						E				
2008:	_	236-12388) 	Verseroe, 340 to	P4 C02				VOLUME SETWE	DI	0,6470	0440	feliti
period:	CBP @ 12100 ==447 =	,						1904090	2 379=4 6	.01400	70.40	.07979
Z/86:			73 tom CC2 .mv	ATRIMO BAL				TRO-CHO				
	Proc Aloks (11362-11369) w/46,5224 Ultu Prop. 223 form CC2, wni 638 bits field. Barrid aut w/2 pag Ultu Prop on formation @ 66776. No Ruth prog/d.							CARACIA				
APRIL:	First Sales (Atalia)			_				PROMOGE				
	, , , , , , , , , , , , , , , , , , , ,							9,00400				
							PERFORATION RE					
							DATE	TOP	1 1701	2008	STATUS	400
							BUAN	12007	120947	Morrow	Abardered	3
							81/04	12912	12516	Morrow	Absorbed	;
							11/23/04	12300	12307	Morrow	Abandanad	;
							11/23/04	12300	12307	Marrie	Abandonad	;
												ı -
							11/30/04	12307	12306	Moren	Abendonad	4
							13/2004	12238	12230	Morrow	Abandoned	4
							6/2/CS	11362	11366	Aleks	Adhre	4
							1	1	l	ı		l
								1	l			
							_	1	l	1		1
							1	1	l	1		l
	Tubing Dotal as of U	3400:	f	SRC WILL			1	1	l	1	1 .	l
	367 En 2 3/6"H-80 Hay Seal Hippin @ 11316"	4 11,010	1	LOOS:	GENCHACCIN					<u> </u>		
				LANDMAR		F Kecr	0E0L0031;	GOODS PENE	Robb Worthings	A		
	1						TUNULA	ID ID	Drift	Collegeor'	Bertf	Tenefir*
	1			Material					One	(pat)	(pet)	(De)
			ì	13.275 (HOLTA)	- 404			12,718	12,960	770	1,730	222,000
				SAME AND LICE				6,821	8.700	2,030	3,830	433,000
			<u></u>					6.300	1			B12,000
				PHOP-HOLTEC	239			6.300	8341	5,000	7,830	B12,000
												l
				45" P110 LT&C 1	1.00			4.000	3.075	7.900	10,680	279.000
				350						l	1	
				2.375" NICOM E	Ø 4.29			1,983	1,301	11,780	11,200	104,300
				* Bafety Factor His								

PREPARED BY: LaAren Heskos DATE: 20/05 Updated: 45/08

R Burdit

OFFICE: @10,163-1701 FAX: @10,001-1702

WELL NAME:	Loving 1 State #4	FIELD: Loving &E	LSES: 025782
STATE:	NM	COUNTY: Eddy	LOCATION: 1980' FSt. & 1980' FEL Sec. 1-248-27E
API NO:	30-015-33084	SPUD DATE: 6/24/00	FORMATION: Atoka
TD:	12872	PBTD: 12056	ELEVATION: 3102 GL



CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)