

Submit 3 Copies

State of New Mexico
Energy, Minerals, and Natural Resources Department

Form C-103
Revised 1-1-89

to Appropriate

District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-021-20134

059

5. Indicate Type of Lease

STATE

FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

BRAVO DOME CO2 GAS UNIT

8. Well No.

1836-361K

9. Pool name or Wildcat

BRAVO DOME CO2 GAS UNIT

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well

OIL WELL

GAS WELL

OTHER CO2

2. Name of Operator

AMOCO PRODUCTION COMPANY

3. Address of Operator

P.O. Box 303, AMISTAD, NEW MEXICO 88410

4. Well Location

Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line
Section 36 Township 18N Range 36E NMPM Union County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4397

GS

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

PLUG AND ABANDON

TEMPORARILY ABANDON

CHANGE PLANS

PULL OR ALTER CASING

OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK

ALTERING CASING

COMMENCE DRILLING OPNS.

PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

OTHER:

12. Describe Proposed or Completed Operations
SEE RULE 1103.

(Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work)

11/17/99
MIRUSU

ENGARD Plug date 03032000

11/18/99

Kill well with fresh water, NUBOP, release packer, lay down production tubing and packer, run CIBP on wireline and set at 2218', run workstring and tag CIBP at 2218', displace casing with fresh water and corrosion inhibitor, pressure test casing to 500 psi, ok. Spot 5 sacks of class C cement from 2218' - 2169', pull workstring to 1652' and spot 15 sacks of cement from 1652' - 1504', pull workstring to 30', spot 5 sacks of cement from 30' - 3', NDBOP, RD MOSU, cut off wellhead, install PXA marker, cut off well anchors and clean location.

2/7/00
OK REF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE D. Holcomb TITLE Field Foreman

DATE 11-19-99

TYPE OR PRINT NAME Danny J. Holcomb

TELEPHONE NO. (505) 374-3010

(This space for State Use)

APPROVED BY [Signature]

TITLE DISTRICT SUPERVISOR

DATE 2/10/00

CONDITIONS OF APPROVAL, IF ANY