

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Red Tank 35 Federal 003	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No. 30-025-33149 (nearest well)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	35	22S	32E	2310	South	990	West	Lea

Latitude N 32.34719° Longitude W 103.65079°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	40 bbls produced water	Volume Recovered	34 bbls produced water
Source of Release	Flange on discharge side of triplex pump ruptured	Date and Hour of Occurrence	04/08/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking-NMOCD, Jennifer Van Curen-BLM			
By Whom?	Jennifer Gilkey	Date and Hour 04/09/2014 @ 5:26 pm			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD; Dr. Oberding at 12:46 pm, Mar 13, 2015



Describe Cause of Problem and Remedial Action Taken.*

The flange on the discharge side of the triplex pump ruptured and caused 40 bbls of produced water to leak onto the ground. 34 bbls were recovered via vacuum truck and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 15' x 40' on location around the pump and some overspray on the East side of the location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by <u>Environmental Specialist:</u> 	
Title: HES Coordinator	Approval Date: 03/13/2015	Expiration Date: 06/13/2015
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval:	
Date: 4-15-14	Site samples required. Delineate and remediate as per NMOCD guides.	Attached <input type="checkbox"/>
Phone: (575) 397-8216		1RP-3562 16696

* Attach Additional Sheets If Necessary

nTO1507246125

pTO1507246310