

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

By OCD; Dr. Oberding at 10:31 am, Mar 19, 2015  
Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Kenny Kidd
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-513-8545
Facility Name	Uncle Sam 13 Fed 1	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-025-30732

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	13	18S	32E	990	North	1980	East	Lea

Latitude: N 32.749"

Longitude: W -103.718

### NATURE OF RELEASE

Type of Release Spill	Mixture of water and oil	Volume of Release	12bbl	Volume Recovered	4.5 bbl
Source of Release	Buried poly line and 2 ft piece of fiberglass pipe and 3 in valve.	Date and Hour of Occurrence	3-17-2015 @ 8:30 am	Date and Hour of Discovery	3-17-2015 @ 8:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Left voicemail with Jim Amos at BLM Left voicemail with Thomas Oberding at OCD		
By Whom?	Ruben Garcia	Date and Hour	3-17-2015 1:20 pm and 1:26 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.\*

#### Describe Cause of Problem and Remedial Action Taken.\*

Devon employees found a 3 inch polyline buried about 3 foot down. The end of the polyline had a union with a 2 foot piece of fiberglass pipe and a 3 inch valve. The fiberglass pipe appeared to have broken away from the fiberglass coupling attached to the union by pressure creating the spill. Devon employees removed the union off of the polyline and replaced it with a 3 inch valve and bull plug stopping the water seepage. This location is Plugged and Abandoned. The spill is on the East side of the location with total of 12 bbls which 4.5 bbls of that went to the pasture on the southeast side of pad. 3 bbl of mixture was picked up by vacuum truck.

#### Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Corina Moya	Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i>
Title: Field Admin Support	Approval Date: 03/19/2015	Expiration Date: 06/19/2015
E-mail Address: corina.moya@dmv.com	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/>
Date: 3-18-2015 Phone: 575.746.5559		IRP-3569 6137

\* Attach Additional Sheets If Necessary

nTO1507838087

pTO1507838329