

**NM1-62**

**Permit  
Application**

**Volume 4  
Part 5 of 11**



Photograph 7. Core sample of claystone with grey clay inclusions (Chinle) in CH-1.



Photograph 8. Core sample at base of CH-1 (Chinle).

## PROJECT PHOTOGRAPHS

SUNDANCE WEST  
SUNDANCE SERVICES INC.  
LEA COUNTY, NEW MEXICO




Gordon Environmental, Inc.  
Consulting Engineers

213 S. Camino del Pueblo  
Bernalillo, New Mexico, USA  
Phone: 505-867-6990  
Fax: 505-867-6991

DATE: 12/03/09	CAD: SSI-PROJECT PICS.doc	PROJECT #: 235.01.02
DRAWN BY: PG	REVIEWED BY: AY	ATTACHMENT A
APPROVED BY: JKG	gei@gordonenvironmental.com	(SHEET 2 OF 9)





Photograph 9. Rodgers set up to drill CH-2.



Photograph 10. Core sample of OAG in CH-2.



Photograph 11. HSA drilling through caliche in CH-2.



Photograph 12. Core sample of CH-2 at the base of the OAG near the top of Chinle.

## PROJECT PHOTOGRAPHS

SUNDANCE WEST  
SUNDANCE SERVICES INC.  
LEA COUNTY, NEW MEXICO



Gordon Environmental, Inc.

Consulting Engineers

213 S. Camino del Pueblo  
Bernalillo, New Mexico, USA  
Phone: 505-867-6990  
Fax: 505-867-6991

DATE: 12/08/09	CAD: SSI-PROJECT PICS.doc	PROJECT #: 235.01.02
DRAWN BY: PG	REVIEWED BY: AV	ATTACHMENT A
APPROVED BY: IKG	gei@gordonenvironmental.com	(SHEET 3 OF 9)