

**NM1 - 33**

---

# **INSPECTIONS & DATA**



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**

Cabinet Secretary

**Mark E. Fesmire, P.E.**

Director

**Oil Conservation Division**

March 3, 2005

Ms. Rebecca J. Doom  
Doom Landfarm  
Box 168  
Jal, NM 88252

Dear Ms. Doom:

The New Mexico Oil Conservation Division (NMOCD) inspected the Doom Landfarm (Doom) facility on February 8, 2005. The NMOCD found the facility to be well maintained and to have good security. It appeared that disking and turning of the soils was being accomplished on a regular basis. No permit deficiencies were found.

The NMOCD would like to take this opportunity to thank Mr. Eddie Seay for his assistance in this inspection.

If you have any questions, contact me at (505) 476-3492 or [emartin@state.nm.us](mailto:emartin@state.nm.us)

NEW MEXICO OIL CONSERVATION DIVISION

Edwin E. Martin  
Environmental Bureau

cc: NMOCD, Hobbs

22-141 50 SHEETS  
22-142 100 SHEETS  
22-144 200 SHEETS



# DOOM LANDFARM LLC

NMOCD Permit # 01-0033

SCC # 2157071

SECTION 5, TOWNSHIP 25 S., RANGE 37 E.

PHONE:

505-631-8314

505-391-9685

505-395-2877



22-141 50 SHEETS  
22-142 100 SHEETS  
22-144 200 SHEETS



Doom LANDFARM  
NM-1-033



# DOOM LANDFARM LLC

NMOCD Permit # 01-0033

SCC # 2157071

SECTION 5, TOWNSHIP 25 S., RANGE 37 E.

PHONE:

505-631-8314

505-391-9685

505-395-2877







DOOM LANDFARM LLC  
BROWNSVILLE, TEXAS 77801  
PHONE: 361-631-1114  
FAX: 361-631-1115

09 17 '03

# DOOM LANDFARM LLC

NMOCD Permit # 01-0033

SCC # 2157071

SECTION 5, TOWNSHIP 25 S., RANGE 37 E.

PHONE:

505-631-8314

505-391-9685

505-395-2877



09 17 03



RECEIVED

SEP 26 2003

OIL CONSERVATION  
DIVISION

September 23, 2003

NMOCD Environmental  
ATTN: Martyne Kieling  
Box 6429  
1220 S. Saint Francis Drive  
Santa Fe, NM 87504


RE: Doom Landfarm #01-0033

Mrs. Kieling:

Pursuant to your inspection and letter, Doom has corrected its sign as you directed. Find attached photos of sign, we had ordered the sign before your inspection, and now have it in place. I hope this corrects our problem.

If you have any questions, please call.

Thanks,



Eddie W. Seay, Agent  
601 W. Illinois  
Hobbs, NM 88242  
(505)392-2236

njk  
10/27/03



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary

August 28, 2003

**Lori Wrotenbery**

Director

**Oil Conservation Division**

Ms. Rebecca J. Doom  
Doom Landfarm, LLC  
Box 168  
Jal, NM 88252

**RE: Doom Landfarm, LLC, Permit NM-01-0033**  
**S/2 NE/4 and N/2 SE/4 of Section 5, Township 25 South, Range 37 East, NMPM,**  
**Lea County, New Mexico**

Dear Ms. Doom:

The New Mexico Oil Conservation Division (OCD) inspected Doom Landfarm, LLC (Doom) on August 12, 2003. The OCD found the facility to be well maintained and have good security (Photos 3, 4 and 5). However, the sign for the facility was missing at the entrance gate (Photo 2). Doom must replace the entrance sign. Tilling and inspection records were reviewed. All tilling and inspections have been performed according to permit requirements (Photo 4). A review of the financial assurance portion of Permit NM-01-0033 finds that a cash bond and assignment in the amount of \$27,833 is on file. This is the full financial assurance amount required by the permit.

Doom shall provide OCD with a description of how the correction will be made and a time-table of when the correction will be completed. Doom must respond to the permit deficiency by September 29, 2003

Please give me a call at (505) 476-3488 if you have any questions.

Sincerely

Martyne J. Kielling

xc with attachment:

Hobbs OCD Office  
Eddie Seay, Agent



Photo 1: Facility sign at the Highway. Contains Facility name, Permit Number, Legal location and Emergency phone numbers. Looking East



Photo 4: Landfarm Cell 1 half full. Looking Southwest.



Photo 2: Facility Sign at Landfarm gate entrance is missing. Looking south into the landfarm.



Photo 5: Landfarm Cell 2 prepared. Looking Northeast.



Photo 3: Facility gate entrance Looking Southeast.