

GW - 37

INSPECTIONS & DATA

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Official Photograph Log



Photo Number: 3 Photographer: T. Reeves, SAIC

Location: Araho, Inc.

Subject: Tank which appears to be leaking oil

City/County: Lea County

State: NM

Date: 11/03/98

Time: pm

Weather: cloudy



Photo Number: 4 Photographer: T. Reeves, SAIC

Location: Araho, Inc.

Subject: Sump full of oil beneath tank valve (measured with stick)

City/County: Lea County

State: NM

Date: 11/03/98

Time: pm

Weather: cloudy

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Official Photograph Log



Photo Number: 1 Photographer: T. Reeves, SAIC

Location: Araho, Inc.

Subject: General facility layout, looking NE

City/County: Lea County

State: NM

Date: 11/03/98 Time: pm

Weather:



Photo Number: 2 Photographer: T. Reeves, SAIC

Location: Araho, Inc.

Subject: General facility layout, looking NE

City/County: Lea County

State: NM

Date: 11/03/98 Time: pm

Weather: cloudy

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Official Photograph Log



Photo Number: 5 Photographer: T. Reeves, SAIC
Location: Araho, Inc.
Subject: Sump full of oil beneath tank valve (measured with stick)
City/County: Lea County State: NM
Date: 11/03/98 Time: pm Weather: cloudy



Photo Number: 6 Photographer: T. Reeves, SAIC
Location: Araho, Inc.
Subject: Pit covered with oil, little freeboard, submerged netting
City/County: Lea County State: NM
Date: 11/03/98 Time: pm Weather: cloudy

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Official Photograph Log



Photo Number: 7 Photographer: T. Reeves, SAIC

Location: Arahq, Inc.

Subject: Placard sign at entrance to facility

City/County: Lea County

State: NM

Date: 11/03/98

Time: pm

Weather: cloudy



Charles 1-27-87



Crabro 1-27-87



Arabo

1-27-87



Arabo

1-27-87



Arabic 1-27-87



Arabo 1-27-87