

1R - 410

REPORTS

DATE:

PHOTOS



H PENROC OIL CORP.
(505) 297-3996
HUTCHERSON A LEASE













051



Oil



Debris

Pits over flowing behind liner



Fence

Oil

Oil


Pits overflowing
behind liner



Oil



Pits overflowing before liner



MESCALERO "ARL" State #1

330' FSL & 330' FEL

Sec. 2 - T10S - R32E

Lea Co. New Mexico

API #30-025-33069 - Lse #VA-0621





