

3R - 281

**GENERAL  
CORRESPONDENCE**

**YEAR(S):**

1992

**MERIDIAN OIL**

IN DIVISION

TO

NOV 9 43

November 5, 1992

Denny Faust  
New Mexico Oil Conservation Division  
1000 Rio Brazos Road  
Aztec, New Mexico 87410

**RE: Olson Groundwater Study and  
Grambling A 3 A**

Dear Mr. Faust:

In response to your request, one Meridian well was included in the Olson report. The Grambling A3A was examined in the William Olson Investigation of Volatile Organic Contamination in Ground Water at Unlined Produced Water Pits. As part of Meridian's standard maintenance procedures, the equipment at this well site has been inspected, repaired or replaced, and painted. The well pad has been cleaned and leveled. The earthen pit on the location was replaced with a below grade 55 BBL fiberglass pit with leak detection. The earthen pit was excavated to receive the fiberglass pit, and all excavated material was thin spread on the well site.

Please call if you have any further questions.

Sincerely,



Derin Warren  
Environmental Representative

cc: VA file,  
Lary Byars

DRW/vka:grambling

