

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2105050187
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party Harvest Midstream Company	OGRID 373888
Contact Name Kijun Hong	Contact Telephone 505-632-4475
Contact email khong@harvestmidstream.com	Incident # (assigned by OCD) nAPP2105050187
Contact mailing address 1755 Arroyo Dr., Bloomfield, NM 87413	

Location of Release Source

Latitude 36.954092 Longitude -108.085317
(NAD 83 in decimal degrees to 5 decimal places)

Site Name Horton Compressor Station	Site Type Compressor Station
Date Release Discovered 2/19/2021- 10:50 am	API# (if applicable) Facility # fCS000000000189

Unit Letter	Section	Township	Range	County
K	27	32N	12W	San Juan

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name): Leshner, James D and Karen C

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) approx. 30	Volume Recovered (bbls) 30
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
<input checked="" type="checkbox"/> Condensate	Volume Released (bbls) approx. 55	Volume Recovered (bbls) 55
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release A tank valve failed due to freezing. Internal corrosion also played a role. The leak has been repaired.

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<div style="display: flex; justify-content: space-between;"><div style="width: 45%;"><p><input checked="" type="checkbox"/> The source of the release has been stopped.</p><p><input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.</p><p><input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.</p><p><input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.</p></div><div style="width: 50%;"><p>If all the actions described above have <u>not</u> been undertaken, explain why:</p><div style="height: 100px; border: 1px solid black; margin-top: 5px;"></div></div></div>	
<p>Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.</p>	
<p>I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.</p>	
<p>Printed Name: <u>Kijun Hong</u></p> <p>Signature: <u></u></p> <p>email: <u>khong@harvestmidstream.com</u></p>	<p>Title: <u>Environmental Specialist</u></p> <p>Date: <u>3/4/2021</u></p> <p>Telephone: <u>505-632-4475</u></p>
<p><u>OCD Only</u></p> <div style="display: flex; justify-content: space-between;"><div>Received by: <u>Ramona Marcus</u></div><div>Date: <u>3/19/2021</u></div></div>	