Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resource	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-045-34239 5. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		0. Same 0.1 60 Gas 2000 1101
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
· ·	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		TSAH TAH 36
1. Type of Well: Oil Well	Gas Well Other	8. Well Number #3
2. Name of Operator		9. OGRID Number
JUNIPER RESOURCES EXP CO 3. Address of Operator	, LLC	10. Pool name or WildcanMOCD
	UITE 300 FORTH WORTH TX 76109	10. Foot fame of whice with the board of the
4. Well Location		111 6.7 2619
Unit Letter_K	feet from theSOUTH lin	e and 1325feet from the
WESTline		DISTRICT
Section 36	Township 25N Range	10W NMPM County SAN JUAN
	11. Elevation (Show whether DR, RKB, RT, GR 6772 GR	R, etc.)
	0772 GR	
12. Check	Appropriate Box to Indicate Nature of No	otice, Report or Other Data
NOTICE OF IN	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL	The state of the s
TEMPORARILY ABANDON		E DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CE	_
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTHER:	☐ OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
JUNIPER RESOURCES REQUESTS APPROVAL TO TEMPORARILY ABANDON THE WELLBORE UNTIL IMPROVED		
ECONOMIC CONDITIONS MERIT RETURNING WELL TO PRODUCTION.		
PROCEDURE:	WIND BODG TRO DUBLINE AND CODARD	TO DEDECRATED BUTERWAL TO MEDITA
MIRU WORKOVER RIG, PULL PUMP, RODS, TBG, RUN BIT AND SCRAPER TO PERFORATED INTERVAL TO VERIFY		
CLEARANCE, RUN AND SET CAST IRON BRIDGE PLUG IN 4-1/2" PRODUCTION CSG, 50' ABOVE TOP PERFORATION (PERFS 1775'-1786'). LOAD CASING WITH TREATED WATER, PRESSURE TEST CASING AND CAST IRON BRIDGE PLUG		
TO 560 PSIG FOR 30 MIN AND RECORD ON 1 HR CHART. LEAVE CAST IRON BRIDGE PLUG IN WELLBORE AND FILE		
CLIDSEOLIENT DEDORT FOR TAXA STATUS WORK TO BE SCHEDULED HILLY 2010		
* Notify the OCD	24hrs prior to the test s	op it can be witnessed
I	1	
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my known	wledge and belief.
A A	A	-1 1-10
SIGNATURE Colon	TITLE ODS ENG	10er/ DATE 72 2019
m		
Type or print name ADAM MARTINEZ E-mail address: ADAM.MARTINEZ@JNPRESOURCES.COM PHONE:505-320-6112		
For State Use Only		
APPROVED BY: 7206	TITLES UP ERVISOR D	DISTRICT #3 DATE 7/10/19
Conditions of Approval (if any):	R	
	1 1	