

May 14, 2007

New Mexico Oil Conservation Division District I 1625 N. French Drive Hobbs, New Mexico 88240

Attn: Environmental Engineering

RE: Remediation Plan South Hobbs Unit 8" Injection Trunk Line 1200 Block of South Hannah Road UL 'L', Sec. 3, T-19-S, R-38-E

Leak occurred on 05/12/2007, at approximately 02:00 PM. An 8" cement lined steel trunk line used to transfer injection water from South Hobbs Unit Central T/B to South Hobbs Unit Injection wells along Leech Street ruptured causing spill. Valves on both ends of the trunk line were shut to isolate leak. The line operates at approximately 1100 pounds and has a rate of approximately 18,000 barrels per day. Produced water ran south on Hannah collecting on both sides due to the street not having curbing. Water also ran down the city street curbing all the way to the intersection of Palace and Rainbow where the water pooled. There were no city sewer drains along the route of the water, please see attached map of the water route. An estimated 320 barrels of injection water was spilled, no oil was spilled. All fluid possible was picked up via vacuum truck, recovering 280 bbls, some may have been rain water. Most fluid was picked up, along both sides of Hannah Road and at the intersection of Palace and Rainbow. Hobbs Fire Department rinsed water route area with Micro Blaze foam to decrease any smell. Damage to area is minimal due to mostly cement and pavement along the water route. Area of spill site will be remediated. Depth to ground water according to State Engineers Office is an average of 46', for all wells in the area, giving this spill site a ranking of 20. Remediation of the spill site will be as follows:

- 1. Piping will be excavated and repaired.
- 2. Soil samples will be gathered from ditch line at spill site.
- 3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.
- 4. Soils removed will be replaced with clean fresh soils, where needed.
- 5. City Streets will be repaired
- 6. Soil analysis data will be submitted with final closure letter.

May 14, 2007 Page 2

.

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.

STEVEN M. BISKLEP

Steven M. Bishop HES Technician/Hobbs RMT Steven_Bishop@oxy.com (505) 397-8251

Attachments: Initial C-141 Hand drawn map of spill site and water route Analytical data of South Hobbs Unit Injection Water dated 03/23/2007

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

	OPERATOR	🛛 Initial Report	Final Report
Name of Company Occidental Permian Limited Partnership	Contact Steven M. Bishop		
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (505) 397-8251		
Facility Name South Hobbs Unit Injection System	Facility Type Production		

Surface Owner City of Hobbs

Mineral Owner

Lease No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
۲,	3	19-S	38-E					LEA

LatitudeN32°41'16.00" LongitudeW103°08'31.30"

NATURE OF RELEASE Volume of Release Est.320 Bbls Type of Release Injection Water Volume Recovered 280 Bbls Date and Hour of Occurrence Source of Release Date and Hour of Discovery 05/12/2007 02:00 PM 05/12/2007 02:00 PM 8" Cement Lined Steel Injection Line If YES, To Whom? Was Immediate Notice Given? Yes No Not Required Mark Whitaker Date and Hour 05/12/2007 03:20 PM By Whom? Steven M. Bishop If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? 🗌 Yes 🖾 No N/A If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* An 8" cement lined steel injection line, buried under Hannah Road, approximately 450' south of the intersection of Hannah Road and Texas Street in Hobbs, New Mexico developed a pin hole causing leak. Valves were closed isolating leak until repairs can be made. All free standing fluid was picked up, via vacuum truck, recovering 280 bbls of water, some possible rain water. Describe Area Affected and Cleanup Action Taken.* Water pooled along Hannah street, adjacent to the leak site and south towards Castle Street. Water also pooled in the intersection of Palace and Rainbow. All free standing fluid was picked up via vacuum truck, mostly gathered along Hannah and at the intersection of Palace and Rainbow. 280 bbls of water was recovered some that may have been rain water. Fire department rinsed water route area with micro blaze foam. Impact was minimal due to water running along curbing and pavement. No city sewer drains were along the route of the water. Hobbs Police and Fire Departments did respond to area. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Steven M. Bishop Expiration Date: 7.22.27 Approval Date: 5 22.07 Title: HES Technician E-mail Address: Steven Bishop@oxy.com Conditions of Approval: Attached 🔲 FUBRUITRE OF FINAL C. 141 Date: 05/14/2007 Phone: (505) 397-8251

* Attach Additional Sheets If Necessary

Midlink -n PACC7/4240186 Copplication - pPACC7/4240324

RU



MITCHELL ANALYTICAL LABORATORY

2638 Faudree XOdessa, Texas 79765-8538 561-5579

Company: Nalco Energy Services

ç

• *

Well Number:	SHU Water Station H-Pump	Sample Temp:	70
Lease:	OXY	Date Sampled:	3/23/2007
Location:		Sampled by:	Kevin Chiles
Date Run:	3/30/2007	Employee #:	
Lab Ref #:	07-mar-n34022	Analyzed by:	DOM

Dissolved Gases

Hydrogen Sulfide) (H29	:)			Mg/L 257.00	Eq. Wt. 16.00	16.06
Carbon Dioxide		<i>יו</i>		YZED	237.00	10.00	10.00
Dissolved Oxvae	n (O2)	-/	NOT ANAL	YZED			
			Cations				
Calcium	(Ca+	-+)			450.24	20.10	22.40
Magnesium	(Mg-	++)			156.16	12.20	12.80
Sodium	(Na+	-)			2,611.43	23.00	113.54
Barium	(Ba+	-+)					
•			NOT ANAL	YZED	•		
Manganese	(Mn-	+)			.01	27.50	.00
			Anions				
Hvdroxvl	(OH-	-)			.00	17.00	.00
Carbonate	(CO:	, 3=)			.00	30.00	.00
BiCarbonate	(HCC)))			1,515.28	61.10	24.80
Sulfate	(SO4	∔=) ́			500.00	48.80	10.25
Chloride	(Cl-)	-		_ <u></u>	4,036.44	35.50	113.70
Total Iron	(Fe)				0.14	18.60	01
Total Dissolved S	Solids				9.526.70	10.00	.01
Total Hardness a	s CaCO3	}			1,765.86		
Conductivity MIC	ROMHO	S/CM			14,460		
pH 7.1	120			Specific (ific Gravity 60/60 F.		
CaSO4 Solubility @ 80 F. 14.84		34	MEq/L,	q/L, CaSO4 scale is unlikel			
CaCO3 Scale Index							
70.0	777	100.0	1 1 2 7	130.0	1.67	7	
80.0	.907	110.0	1.367	140.0	1.63	7 7	
90.0	1.127	120.0	1.367	150.0	1.86	57	

Nalco Energy Services