

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: J&J Service, Inc.	Contact: Jerry Carlisle	
Address: 8428 W. Sumruld Rd., Lovington, NM 88260	Telephone No.: (575)369-9230	
Facility Name: Jones 34 Federal #1 Battery	Facility Type: Exploratory & Production	
Surface Owner: R.B. Jones	Mineral Owner: Federal	API No. 30-025-29832

**LOCATION OF RELEASE**

Unit Letter "N" (SE/SW)	Section 34	Township 14S	Range 35E	Feet from the 720	North/South Line North	Feet from the 465	East/West Line East	County Lea
----------------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude 33.055491° Longitude -103.396796°

**NATURE OF RELEASE**



Type of Release Crude oil	Volume of Release 196 bbls	Volume Recovered 40 bbls
Source of Release Bull Plug on 2" Roll Line	Date and Hour of Occurrence 2/20/15, Time Unknown	Date and Hour of Discovery 2/20/15, 19:30
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

**HOBBS OCD**  
MAY 15 2015

Describe Cause of Problem and Remedial Action Taken.\*  
During a routine site visit, a bull plug from a 2" roll line was found on the ground next to an on-site storage tank. Vandalism is suspected. During initial response activities, the storage tank was valved off, and the bull plug was replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The release impacted approximately 9,400 sq.ft. of the tank battery pad and the adjacent pasture. Vacuum trucks were utilized to recover free-standing liquid. The affected area will be remediated in accordance with NMOC guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ben J. Arguijo (agent of J&J Service, Inc.)	Approved by Environmental Specialist: 	
Title: Project Manager, Basin Environmental	Approval Date: 05/18/2015	Expiration Date: 08/18/2015
E-mail Address: bjarguijo@basinenv.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOC guidelines. Geotag photographs of remediation required.	Attached <input type="checkbox"/> 11095 IRP-3635
Date: 5/14/2015 Phone: (575)396-2378		

\* Attach Additional Sheets If Necessary

**REVIEWED**

By OCD District 1 at 7:18 am, May 18, 2015

pKJ1513828757  
nKJ1513827926