

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	(575) 397-8251
Facility Name	NHU 24-342	Facility Type	Injection Trunk Line
Surface Owner	Mineral Owner	API No.	30-025-29062

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	25	18S	37E					Lea County, NM

Latitude N 32.72122° Longitude W 103.20383°

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	145 bbls	Volume Recovered	45 bbls
Source of Release	Internal corrosion of a 4" steel injection trunk line	Date and Hour of Occurrence	05/10/2015 @ 10:30 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding- NMOCD via email on 05/10/2015		
By Whom?	Tony Aguilar, Oxy	Date and Hour	05/10/2015 @ 12:19 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**REVISED**

10:04 am, Jun 23, 2015

This is revision from the previously version dated 28 May 15.


Describe Cause of Problem and Remedial Action Taken.\*

A 4" steel line leaked due to internal corrosion causing 145 bbls of produced water to leak onto the ground. A vacuum truck recovered 45 bbls of water and as of 05/28/2015 the line is being repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is approximately 110' x 325' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Tony Aguilar	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date:	Expiration Date:	
E-mail Address: Raymond_aguilar@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 6-23-15	Phone: (575) 397-8251		

\* Attach Additional Sheets If Necessary

**RECEIVED**

By OCD District 1 at 10:04 am, Jun 23, 2015