

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian	Contact	Tony Aguilar
Address	1017 W. Stanolind Road	Telephone No.	(575) 397-8251
Facility Name	SHU #172 Injection line	Facility Type	Injection
Surface Owner	Mineral Owner	API No.	30-025-28543

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
NE ¼	9	19S	38E					Lea County, NM

Latitude N 32.68019° Longitude W 103.147789°

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	150 bbls	Volume Recovered	0 bbls
Source of Release	Stress/fatigue of a 4" fiberglass injection line	Date and Hour of Occurrence	07/11/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones- NMOCD		
By Whom?	Tony Aguilar, Oxy	Date and Hour	07/11/2015		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By OCD District 1 at 1:27 pm, Jul 16, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Stress or fatigue of a 4" fiberglass injection line caused 150 bbls of produced water to spill onto the ground. No fluids were recovered and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*

The area affected is approximately 100' x 75' on location to the east of the SHU water injection bldg. and into the trench. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Tony Aguilar	Approved by Environmental Specialist: 		
Title: HES Specialist	Approval Date: 07/16/2015	Expiration Date: 10/16/2015	
E-mail Address: Raymond_aguilar@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 7-16-15 Phone: (575) 397-8251	Discrete site samples required. Delineate and remediate per NMOCD guides. Geotagged photos of remediation required.	ogrid 157984 1RP 3736	

\* Attach Additional Sheets If Necessary

pJXK1519748992

nJXK1519748730