

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By OCD District 1 at 7:39 am, Aug 17, 2015

Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Proximity 31 Federal #4 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-20423

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	22S	32E					Lea County, NM

Latitude N 32.35339° Longitude W 103.71131°

### NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10 bbls oil and 100 bbls produced water	Volume Recovered	5 bbls oil, 100 bbls produced water
Source of Release	Stress/fatigue of an 8" fiberglass suction line off a tank	Date and Hour of Occurrence	07/27/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kellie Jones, Jamie Keyes, & Tomas Oberding-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	7/28/2015 @ 3:28 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By OCD District 1 at 7:39 am, Aug 17, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Stress/fatigue of an 8" fiberglass suction line off of a tank caused 10 bbls of oil and 100 bbls of produced water to leak onto the ground. A vacuum truck recovered 5 bbls of oil and 100 bbls of produced water and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 50' x 25' on location inside the firewall. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: CJ Summers	Approved by Environmental Specialist: 		
Title: HES Lead	Approval Date: 08/17/2015	Expiration Date: 10/17/2015	
E-mail Address: chancey_summers@oxy.com	Conditions of Approval: Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photos of remediation required. Ensure BLM concurrence/approval.		Attached <input type="checkbox"/> IRP 3802
Date: 8-13-15	Phone: (432) 685-5824		

\* Attach Additional Sheets If Necessary

pJXK1522927393

nJXK1522927214