


**REVIEWED**

By OCD District 1 at 11:18 am, Sep 18, 2015

**INFORMATION ONLY**

**NOT APPROVED**
















Tank that was  
hit by lightning

Spill Path

where spill stopped  
in pasture.

Sample spots

Entrance







# PANTHER ENERGY SERVICES, LLC

P.O. BOX 1321 JAL N.M. 88252 PHONE: 575-395-2654 FAX: 575-395-2162

## Title

Date: 9-17-15

Company Name: Fulfer Oil + Cattle

Lease Name: South Langlie Jal Unit Injection Station

Section: 7

Township: 25 S

Range: 37 E

RP # 3831

## Work Plan

500 bbl fiberglass tank was struck by lightning causing the spill. The affected area is approximately 50' x 50' outside battery. No remedial activities have taken place. One call has been submitted. We will push up top soil of affected area. Then we will take PIS samples of area to find and clean up any hot spots left. Finally, we will take a composite sample of the area to see if clean. Sample will be taken to lab for verification. If clean we will backfill area.