

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Occidental Permian LTD	Contact Steven M. Bishop	
Address 1017 West Stanolind Road, Hobbs, N.M. 88240	Telephone No. (575) 397-8235	
Facility Name South Hobbs Unit Central Tank Battery	Facility Type Oil and Gas Production Facility	
Surface Owner OXY PERMIAN	Mineral Owner OXY	Lease No.

LOCATION OF RELEASE

Unit Letter A	Section 9	Township 19-S	Range 38-E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
------------------	--------------	------------------	---------------	---------------	------------------	---------------	----------------	---------------

Latitude 32.40'48.69" Longitude 103.08'52.64"

NATURE OF RELEASE

Type of Release Flare	Volume of Release 2160.54 mcf	Volume Recovered 0
Source of Release Flare	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Maxey Brown via C-129	
By Whom? Tony Aguilar	Date and Hour 7/6/2015 at 9:25 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

RECEIVED

By JKeyes at 8:04 am, Sep 25, 2015

Describe Cause of Problem and Remedial Action Taken.*



Cause: DCP shut in the gas gathering system to their Eunice Plant, due to their Sulfur Recovery Unit having to be shut down for repair.

Remedial Action Taken: Oxy shut in high GOR wells to reduce volume. DCP reopened gas gathering system after repairs made. Flare eliminated upon opening of gas gathering system.

Describe Area Affected and Cleanup Action Taken.*

All gas burned at flare.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Steven M. Bishop	Approved by District Supervisor: 	
Title: HES Advisor	Approval Date: 09/25/2015	Expiration Date: ///
E-mail Address: Steven_Bishop@oxy.com	Conditions of Approval: ///	Attached <input type="checkbox"/> IRP 3883
Date: 08/24/2015	Phone: (575) 397-8235	

* Attach Additional Sheets If Necessary

pJXK1526829015

nJXK1526828911