<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action													
							OR		Initial	Report	☐ Final	Report	
Name of Co	ompany l	Linn Operati			Contact E.L. Gonzales								
Address 2	130 W Be	nder Blvd H	M 88240		Telephone No. 575-738-1739								
Facility Nat CMU A #14		N. Inj Statio	Line (Closest w	ell	Facility Type Injection								
Surface Owner State Mineral Owner							API No. closest well 30-025-32923						
LOCATION OF RELEASE													
Unit Letter H	Section 18	Township 17S	Range 33E	Feet from the 2618		South Line North	Feet from the 88		East/West Line County East				
Latitude 32.8346519 Longitude -103.6942825													
NATURE OF RELEASE Type of Release Produced Water Volume of Release 7 bbls Volume Recovered .5 bbl.													
Type of Release Produced Water Source of Release FG- pipeline											Hour of Discovery		
Source of Actease 1.0- piperine							10/17/2015 10/17/2015 1:3						
Was Immediate Notice Given? Yes No Not Required						If YES, To Whom?							
By Whom?						Date and Hour							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. RECEIVED							
If a Watercourse was Impacted, Describe Fully.*							JKeyes at	t 2 :01	pm, (Oct 20,	2015		
Describe Cause of Problem and Remedial Action Taken.* Received an alarm callout at approximately 1:30am for a pump failure. Upon arrival to location we noticed that the pump had turned off and we had lost pressure from the pump. This gave evidence that we had some type of release out in the field. We promptly shut in our injection lines and began searching for the release. Finding the leak however proved difficult due to the amount of visibility we had since it was dark outside. After several hours of searching we narrowed down the area where we believed the leak was in. Once the sun began to rise we were able to locate the release and found it just south of the CMU-A #140, or north of the CMU-A #151, or east of the CMU-A #18, or West of the CMU-A #19 to be exact. The release came from a 4 inch fiberglass T that gave way and caused the fluid to leak out. Describe Area Affected and Cleanup Action Taken.* The release itself was approximately 65ft long with the widest point going 10 ft. wide to the north of the release point and 5ft south of the actual release point for a total wide point of 15ft. The estimated amount lost is 7bbls with an estimated 1/2bbl recovered with a vac truck.													
regulations a public health should their or or the environ	Il operators or the envi operations h nment. In a	are required to ronment. The tave failed to a	o report an acceptand adequately OCD accep	e is true and comp nd/or file certain rece of a C-141 report investigate and report otance of a C-141	elease no ort by the emediate	otifications a e NMOCD m e contaminati	nd perform correct parked as "Final R ion that pose a three the operator of	etive acti eport" de reat to gre responsi	ons for relections not relictions ound water bility for contractions.	eases which reve the opera , surface wat ompliance wi	may endang ator of liabi er, human l ith any othe	er lity nealth	
							OIL CONSERVATION DIVISION						
Signature: Printed Name: E.L. Gonzales							Approved by Environmental Specialist:						
							Approval Date: 10/20/2015 Expiration Date: 12/20/2015			2015			
						Conditions of Approval: Discrete site samples required. Delineate and Attached							
							emediate per NMOCD guidelines. 1RP 3931						





