

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	432-685-5771
Facility Name	MLMU CTB	Facility Type	Battery
Surface Owner	Jimmy Doom	Mineral Owner	
		API No.	30-025-11017

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	24S	37E					Lea

Latitude 32.24724 Longitude 103.18388

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	30 bbls oil, 30 bbls produced water	Volume Recovered	55 bbls of fluid
Source of Release	Lost pressure on the belts of the supplied gas air compressor sent the fluid out the vent line and relief valve	Date and Hour of Occurrence	10/23/15	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Kelly Jones, Jamie Keyes		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	10/23/15 2:32 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**RECEIVED**

By Kellie Jones at 11:22 am, Nov 12, 2015



Describe Cause of Problem and Remedial Action Taken.\*

Lost pressure on the belts of the supplied gas air compressor which sent fluid out the vent line and relief valve caused the spill of 30 bbls oil and 30 bbls produced water. A vacuum truck recovered 55 bbls of fluid.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 200' x 100' on location. Remediation will be completed in accordance with the remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Dusty Wilson		Approved by Environmental Specialist: 	
Title: Environmental Advisor		Approval Date: 11/12/2015	Expiration Date: 01/12/2016
E-mail Address: : Dusty.Wilson@oxy.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation required.		Attached <input type="checkbox"/> IRP-3978
Date: 11/11/15	Phone:		

\* Attach Additional Sheets If Necessary

nKJ1531641073  
pKJ1531641656