

**RECEIVED**

By JKeyes at 7:17 am, Feb 08, 2016

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action****OPERATOR**

☒ Initial Report ☐ Final Report



Name of Company	Holloman Corp.	Contact	Dennis Hedger
Address	16410 US-380 Krum, TX 76249	Telephone No.	817-825-8867
Facility Name	EMSU 621 (XTO)	Facility Type	
Surface Owner	State	Mineral Owner	API No. 30-025-33186

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	6	21S	36E	2800	South	185	East	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	65 bbls of oil and water	Volume Recovered	61bbls of oil and water
Source of Release	Flow Line	Date and Hour of Occurrence	1-24-16 7:00am	Date and Hour of Discovery	1-24-16 7:30 am
Was Immediate Notice Given?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* Holloman employee was notified by XTO of a leaking line. The area of the leak had been previously backfilled on 01/22/16 by Holloman. An XTO crew was onsite and contained and isolated the lines. XTO crews exposed and repaired 2 fiberglass lines and one line was found to be cracked. Another line leak was found approximately 50 feet from this location on 1/23/16 and a hydrovac truck had been parked in the location of this leak. Prior to these incidents, Holloman had struck 2 unmarked/unlocated fiberglass lines in the area belonging to XTO.					
Describe Area Affected and Cleanup Action Taken.* The incident occurred on pipeline right-of-way and was contained to that right-of-way. Leaked product was removed by hydrovac and contaminated soil was properly removed.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Jackie Harrell		Approved by Environmental Specialist: 			
Title: Division Safety Manager		Approval Date: 02/08/2016		Expiration Date: 04/08/2016	
E-mail Address: jackieharrell@hollomancorp.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 02/03/16 Phone: 940-482-3442		Discrete site samples only. Delineate and remediate per NMOCD guidelines.		IRP 4155	

\* Attach Additional Sheets If Necessary

nJXK1603925859  
pJXK1603926101