

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 8:06 am, May 25, 2016

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: <b>Energy Transfer Field Services LLC</b>	Contact: <b>Johnnie Bradford</b>	
Address: <b>600 N. Marienfeld Street</b>	Telephone No. <b>(432) 250-5542 (cell) (817) 302-9812 (off)</b>	
Facility Name:	Facility Type: <b>Pipeline</b>	
Surface Owner: <b>Miller Deck Estate</b>	Mineral Owner:	API No.

#### LOCATION OF RELEASE

Unit Letter <b>J</b>	Section <b>22</b>	Township <b>21S</b>	Range <b>37E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Lea</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude 32.46435N Longitude 103.15003W

#### NATURE OF RELEASE

Type of Release: <b>Gas</b>	Volume of Release: <b>84 Mscf - 2-3 bbls of Spray</b>	Volume Recovered: <b>None</b>
Source of Release: <b>Pipeline - Number 1023</b>	Date and Hour of Occurrence: <b>05/18/2016 06:00</b>	Date and Hour of Discovery: <b>05/18/2016 06:00</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>N/A</b>	
By Whom? <b>N/A</b>	Date and Hour: <b>N/A</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	

If a Watercourse was Impacted, Describe Fully.\*

Watercourse was not affected. There was a small amount of liquid that was released as a spray to the surrounding area.



Describe Cause of Problem and Remedial Action Taken.\*

The polymer pipeline developed a crack that opened to spray vaporized liquid and gas on the surrounding area. The area around the leak was uncovered and the leak clamped. As time allows this section of pipeline will be replaced.

Describe Area Affected and Cleanup Action Taken.\*

Area that was sprayed with vaporized liquid will be scraped and treated with a microbial surfactant to aid in the remediation of the affected surface area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Johnnie Bradford</b>	Approved by Environmental Specialist: 	
Title: <b>Sr. Environmental Specialist</b>	Approval Date: <b>05/25/2016</b>	Expiration Date: <b>///</b>
E-mail Address: <b>johnnie.bradford@energytransfer.com</b>	Conditions of Approval: <b>///</b>	Attached <input type="checkbox"/> <b>1RP 4293</b>
Date: <b>05/24/2016</b>	Phone: <b>(432) 250-5542</b>	

\* Attach Additional Sheets If Necessary

nJXK1614628853  
pJXK1614628992