

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

By JKeyes at 7:54 am, Aug 22, 2016

Form C-141  
Revised August 8, 2011

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Endeavor Energy Resources	Contact: Ashley Moore	
Address: 110 N Marienfeld, Suite 200, Midland, TX 79706	Telephone No. (432) 557-5006	
Facility Name: Harton State #1 & #2 Tank Battery	Facility Type: Battery	
Surface Owner: William Paige McNeill	Mineral Owner	API No. 30-025-28540

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	7	13S	36E					Lea County, NM

Latitude N 33.20734° Longitude W 103.33786°

### NATURE OF RELEASE

Type of Release Oil and Produced water	Volume of Release 16 bbls oil, 60 bbls produced water	Volume Recovered 45 bbls
Source of Release Water leg on heater treater was plugged, sending water to the oil tank causing an overflow	Date and Hour of Occurrence 08/15/2016	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes, Kristen Lynch-NMOCD	
By Whom? Jennifer Gilkey, BBC International Inc.	Date and Hour 08/16/2016 @ 5:05 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The water leg on the heater treater was plugged, send excess water to the oil tank, causing it to overflow and leak 16 bbls of oil and 60 bbls of produced water. A vacuum truck recovered 45 bbls of fluid and the water leg was returned to service.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is 50' x 40' inside the berm of the battery on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ashley Moore		Approved by Environmental Specialist: 	
Title: Environmental Technician		Approval Date: 08/22/2016	Expiration Date: 10/22/2016
E-mail Address: APMoore@eeronline.com		Conditions of Approval: Discrete samples only. Delineate and remediate per NMOCD guidelines.	Attached <input type="checkbox"/> 1RP 4407 pJXK1623528363 nJXK1623528218
Date: 8/19/16	Phone: (432) 557-5006		

\* Attach Additional Sheets If Necessary